Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an . Lease Serial No. NMSF078139

abandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well	8. Well Name and No.	
☐ Oil Well ☐ Gas Well ☒ Other: INJECTION	EE ELLIOT SWD SWD 1	
2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPANYMail: Toya.Colvin@bp.com	9. API Well No. 30-045-27799-00-S1	
3a. Address 501 WESTLAKE PARK BLVD. THREE ELDRIGE PLACE: 281.892.5369 HOUSTON, TX 77079	10. Field and Pool or Exploratory Area UNNAMED	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State	
Sec 26 T30N R9W NWNW 1270FNL 0580FWL 36.786040 N Lat, 107.763810 W Lon	SAN JUAN COUNTY, NM	

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

12. CHECK THE MITKOTKITTE BOX(ES) TO INDICATE PARTOKE OF POTTER BATTAT							
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off□ Well Integrity☑ OtherWorkover Operations			

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BP would like to re-perforate across the existing intervals the subject well. Please see the attached procedure including wellbore diagrams.

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OIL CONS. DIV DIST. 3

OCT 05 2017

14. I hereby certify that the foregoing is true and correct. Electronic Submission #389872 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 09/27/2017 (17JWS0223SE)						
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST			
Signature	(Electronic Submission)	Date	09/26/2017			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By JACK SAVAGE Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			ETROLEUM ENGINEER Farmington	Date 09/27/2017		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United						

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



4

EE Elliott SWD #1

API # 30-045-27799-00

Location: Unit D - Sec 26 - T30N - R09W

San Juan County, New Mexico


Reason/Background for Job

The proposed work is to re-perforate across the existing completion to help increase injectivity.

Basic job procedure

- 1. Rig up E-line
- 2. Selectively perforate between 7564' and 8418'
- 3. File post job Sundry
- 4. Return the well to operation

Current WBD



Proposed WBD

