Form 3160-5					
(June 2015)	UNITED STATES DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEME			ON Expi 5. Lease Serial No.	RM APPROVED MB No. 1004-0137 res: January 31, 2018
Do not use	RY NOTICES AND REP this form for proposals vell. Use Form 3160-3 (A	to drill or to re	-enter an	N0G14031948 6. If Indian, Allottee or	Tribe Name
SUBM	IT IN TRIPLICATE - Other instru Gas Well	ructions on page 2		7. If Unit of CA/Agreen	nent, Name and/or No.
1. Type of Well		OIL	CONS. DIV DIS		
			DEC.	The spinor of the state	
2. Name of Operator WPX Energy Production, LLC		DEC 2 2 2017		9. API Well No. 30-045-35813	
3a. Address PO Box 640 Aztec, NM 87410		3b. Phone No. <i>(include area code)</i> 505-333-1816		10. Field and Pool or Exploratory Area Lybrook Mancos W	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1835' FSL & 624' FEL Sec 14 T23N R9W Unit: I BHL: 1562' FSL & 335' FWL Sec 11 T23N R9W Unit: L		-		11. Country or Parish, State San Juan, NM	
12.	CHECK THE APPROPRIATE B	OX(ES) TO INDICA	TE NATURE OF NOT	CE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION			TYPE OF ACT	ION	
Notice of Intent	Acidize	Deepen		duction (Start/Resume)	□ Water ShutOff
	Alter Casing	Hydraulic Frac		lamation	Well Integrity
Subsequent Report	Casing Repair	New Construc		omplete	Other <u>COMPLETION</u>
Final Abandonment Notice	Change Plans	Plug and Abar	a chi	nporarily Abandon er Disposal	
P	Convert to injection	Plug Back		ci Disposai	
61					
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.)	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports w interval, a Form 3160-4 must be file and the operator has detennined that the	sured and true vertical d s must be filed within 30 d once testing has been o e site	epths of all pertinent marked days following completion completed. Final Abandonn	ers and zones. Attach the Bon a of the involved operations. I nent Notices must be filed on	f the operation results in a multiple y after all requirements, including
directionally or recomplete horizon provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PS <u>I 4-1/2" casi</u>	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports ew interval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3	sured and true vertical d s must be filed within 30 d once testing has been o e site 30 Min GOOD TEST	epths of all pertinent marked days following completion completed. Final Abandonn	ers and zones. Attach the Bon a of the involved operations. I nent Notices must be filed on	d under which the work will be performed f the operation results in a multiple y after all requirements, including
directionally or recomplete horizon provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PS <u>L4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports ew interval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes	sured and true vertical d s must be filed within 30 d once testing has been o e site 30 Min GOOD TEST	epths of all pertinent marked days following completion completed. Final Abandonn	ers and zones. Attach the Bon of the involved operations.	d under which the work will be performed f the operation results in a multiple y after all requirements, including
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PS <u>L 4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on fra	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports ew interval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes	sured and true vertical d s must be filed within 30 d once testing has been of e site 0 Min GOOD TEST 5. DEC 19 mted/Typed)	epths of all pertinent marked days following completion completed. Final Abandonn 2007 2017 2017 2017	ers and zones. Attach the Bon a of the involved operations. I nent Notices must be filed on	d under which the work will be performed f the operation results in a multiple y after all requirements, including
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PS <u>I 4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on fra	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports we interval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes	sured and true vertical d s must be filed within 30 d once testing has been of e site 00 Min GOOD TEST 5. DEC 18 nted/Typed) Title	epths of all pertinent marked days following completion completed. Final Abandonn	ers and zones. Attach the Bon n of the involved operations. I nent Notices must be filed on MATALE	d under which the work will be performed f the operation results in a multiple y after all requirements, including MARECEIVED DEC 13 2017 Farmington Field Office
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PSL4-1/2" casi Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on fra 14. I hereby certify that the forego Lacey Granillo	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports winterval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes ac	sured and true vertical d s must be filed within 30 d once testing has been of e site 0 Min GOOD TEST 5. DEC 18 DEC 18 Inted/Typed) Title	epths of all pertinent marked days following completion completed. Final Abandonn 2007 2007 2007 2007 2007 2007 2007 20	ers and zones. Attach the Bon n of the involved operations. I nent Notices must be filed on COMFIDENT	d under which the work will be performed f the operation results in a multiple y after all requirements, including MARECEIVED DEC 13 2017
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PSL <u>4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on frac 14. I hereby certify that the forego Lacey Granillo Signature	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports winterval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes ac	sured and true vertical d s must be filed within 30 d once testing has been of e site 0 Min GOOD TEST 5. DEC 18 DEC 18 Inted/Typed) Title	epths of all pertinent marked days following completion completed. Final Abandonn CORECORD	ers and zones. Attach the Bon n of the involved operations. I nent Notices must be filed on COMFIDENT	d under which the work will be perfonned f the operation results in a multiple y after all requirements, including MARECEIVED DEC 13 2017 Farmington Field Office
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PS <u>L4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on fra 14. I hereby certify that the forego Lacey Granillo	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports winterval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes ac	sured and true vertical d s must be filed within 30 d once testing has been of e site 0 Min GOOD TEST 5. DEC 18 DEC 18 Inted/Typed) Title	epths of all pertinent marked days following completion completed. Final Abandonn 2007 2007 2007 2007 2007 2007 2007 20	ers and zones. Attach the Bon a of the involved operations. I nent Notices must be filed on COMANDENT	d under which the work will be performed f the operation results in a multiple y after all requirements, including MCRECEIVED DEC 13 2017 Farmington Field Office Ireau of Land Management
directionally or recomplete horizor provide the Bond No. on file with completion or recompletion in a ne reclamation, have been completed is ready for final inspection.) 10/6/17- MIRU. PSL <u>4-1/2" casi</u> Perf MC 1 st stage, 11866'-11870 10/7/17-10/24/17- Wait on fra 14. I hereby certify that the forego Lacey Granillo Signature Approved by Conditions of approval, if any, are	tally, give subsurface locations and mea BLM/BIA. Required subsequent reports we interval, a Form 3160-4 must be filed and the operator has detennined that the ng Test Casing @ 6,500#s for 3 0' RSI TOOL with 8, 0.35" holes and ing is true and correct. Name (Print THE SPACE e attached. Approval of this notice of gal or equitable title to those rights	sured and true vertical d s must be filed within 30 d once testing has been of e site 0 Min GOOD TEST 5. DEC 19 nted/Typed) Title Date E FOR FEDERA	epths of all pertinent marked days following completion completed. Final Abandonn 2007 2007 2007 2007 2007 2007 2007 20	ers and zones. Attach the Bon n of the involved operations. I nent Notices must be filed on COMFIDENT	d under which the work will be perfonned of the operation results in a multiple y after all requirements, including

NMOCD

W Lybrook Unit 716H

10/25/17- PSI Test All Lines Up To 9,250 Lbs, Test Good

Frac MC 1st stage 11866'-11870' - 8, 0.35" holes, 1st stage with 60000 # 20/40 PSA Sand Perf 2nd stage 11659'-11816'-with 20, 0.35" holes. Frac MC 2nd stage with 205000#, 20/40 PSA Sand 10/26/17-Perf 3rd stage 11451'-11608'- with 20, 0.35" holes. Frac MC 3rd stage with 205200#, 20/40 PSA Sand Perf 4th stage 11243'-11400'- with 20, 0.35" holes. Frac MC 4th stage with 205000#, 20/40 PSA Sand Perf 5th stage 11035'-11192'-with 20, 0.35" holes. Frac MC 5th stage with 205000#, 20/40 PSA Sand Perf 6th stage 10827'-10984'- with 20, 0.35" holes. Frac MC 6th stage with 206200#, 20/40 PSA Sand 10/27/17-Perf 7th stage 10619'-10776'- with 20, 0.35" holes. Frac MC 7th stage with 204900#, 20/40 PSA Sand Perf 8th stage 10411'-10568'- with 20, 0.35" holes. Frac MC 8th stage with 205000#, 20/40 PSA Sand Perf 9th stage 10203'-10360'- with 20, 0.35" holes. Frac MC 9th stage with 205000#, 20/40 PSA Sand Perf 10th stage 9995'-10152'- with 20, 0.35" holes. Frac MC 10th stage with 205000#, 20/40 PSA Sand Perf 11th stage 9787'-9944'- with 20, 0.35" holes. Frac MC 11th stage with 205400#, 20/40 PSA Sand Perf 12th stage 9579'-9736'- with 20, 0.35" holes. Frac MC 12th stage with 205400#, 20/40 PSA Sand 10/28/17-Perf 13th stage 9371'-9528'- with 20, 0.35" holes. Frac MC 13th stage with 206000#, 20/40 PSA Sand Perf 14th stage 9163'-9320'- with 20, 0.35" holes. Frac MC 14th stage with 205500#, 20/40 PSA Sand 10/29/17-Perf 15th stage 8955'-9112'- with 20, 0.35" holes. Frac MC 15th stage with 204900#, 20/40 PSA Sand Perf 16th stage 8747'-8904'- with 20, 0.35" holes. Frac MC 16th stage with 205200#, 20/40 PSA Sand Perf 17th stage 8539'-8696'- with 20, 0.35" holes. Frac MC 17th stage with 205000#, 20/40 PSA Sand Perf 18th stage 8331'-8488'- with 20, 0.35" holes. Frac MC 18th stage with 205000#, 20/40 PSA Sand Perf 19th stage 8123'-8280'- with 20, 0.35" holes. Frac MC 19th stage with 205000#, 20/40 PSA Sand 10/30/17-Perf 20th stage 7915'-8072'- with 20, 0.35" holes. Frac MC 20th stage with 205000#, 20/40 PSA Sand Perf 21st stage 7707'-7864'- with 20, 0.35" holes. Frac MC 21st stage with 205000#, 20/40 PSA Sand Perf 22nd stage 7499'-7656'- with 20, 0.35" holes. Frac MC 22nd stage with 205000#, 20/40 PSA Sand Perf 23rd stage 7291'-7448'- with 20, 0.35" holes. Frac MC 23rd stage with 205000#, 20/40 PSA Sand Perf 24th stage 7083'-7240'- with 20, 0.35" holes. Frac MC 24th stage with 204900#, 20/40 PSA Sand 10/31/17-Perf 25th stage 6880'-7032'- with 20, 0.35" holes. Frac MC 25th stage with 204600#, 20/40 PSA Sand Perf 26th stage 6667'-6824'- with 20, 0.35" holes. Frac MC 26th stage with 204300#, 20/40 PSA Sand Perf 27th stage 6459'-6616'- with 20, 0.35" holes. Frac MC 27th stage with 206500#, 20/40 PSA Sand Perf 28th stage 6251'-6408'- with 20, 0.35" holes. Frac MC 28th stage with 204300#, 20/40 PSA Sand Perf 29th stage 6043'-6200'- with 20, 0.35" holes. Frac MC 29th stage with 205500#, 20/40 PSA Sand 11/1/17-Perf 30th stage 5835'-5992'- with 20, 0.35" holes. Frac MC 30th stage with 203500#, 20/40 PSA Sand Perf 31st stage 5627'-5784' with 20, 0.35" holes. Frac MC 31st stage with 204100#, 20/40 PSA Sand Perf 32nd stage 5419'-5576'- with 20, 0.35" holes. Frac MC 32nd stage with 204800#, 20/40 PSA Sand Set Kill plug @ 5369'

RDMO

11/2/17-11/8/17- wait on DO

11/9/17-11/12/17- MIRU- DO Frac plugs. Pull tie back. RSI

11/13/17- Start RIH

11/14/17-Land Production string /Gas lift system. Landed @ 5229'. 155 Jnts of 2 7/8" 6.5# j-55 & 4 jts of 2 3/8" 6.5# L-80. Packer set @ 5097', 8 Gas Lift Valves

11/15/17-11/24/17-flow back

11/25/17- Oil Delivery

Choke Size= 40/64", Tbg Prsr=523, Csg Prsr= 657 psi, Sep Prsr= 137 psi, Sep Temp= 89 degrees F, Flow Line Temp= 0 degrees F, Flow Rate= 1356 mcf/d, 24hr Fluid Avg= 71.54 bph, 24hr Wtr= 474 bbls, 24hr Wtr Avg= 19.75 ph, Total Wtr Accum= 4423 bbls, 24hr Oil= 1243 bbls, 24hr Oil Avg= 51.79 bph, 24hr Fluid= 1717bbls