Form 3160-5 (June 2015)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20

LAPITOS. Jul	٨,
Lease Serial No.	
NIMACEOZOOGE	

SUNDRY	5. Lease Serial No. NMSF078095								
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name								
SUBMIT IN T		7. If Unit or CA/Agreement, Name and/or No.							
Type of Well ☐ Gas Well ☐ Oth		8. Well Name and No. CASE B 21							
Name of Operator BP AMERICA PRODUCTION		9. API Well No. 30-045-27777-00-S1							
3a. Address 380 AIRPORT RD DURANGO, CO 81303	3b. Phone No. (include area code) Ph: 281.892.5369			10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	1)			11. County or Parish, State				
Sec 18 T31N R11W SENE 16 36.901260 N Lat, 108.025955					SAN JUAN COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	☐ Acidize	□ Deep	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hyd	raulic Fracturin	Fracturing Reclamation		■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Tempor	arily Abandon				
BR	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.									
BP requests to P&A the subject well. Please see the attached P&A procedure, wellbore diagram, and BLM required reclamation plan documents.									
In accordance with NMOCD P	rit Rule 19.15.17.9 NMAC	C, BP will use a	a closed-loop	system during					
operations. NMOCD									
and the second of the second o	Notify NMOCD 24 hrs prior to beginning operations	ום	AUG 02						
14. I hereby certify that the foregoing is true and correct. Electronic Submission #422755 verified by the BLM Well Information System									
For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 07/31/2018 (18JWS0164SE)									
Name (Printed/Typed) TOYA CO		cooning by or		JLATORY AN					
Signature (Electronic S	Submission)		Date 06/06	/2018					
			00/00						

THIS SPACE FOR FEDERAL OR STATE OFFICE USE TitlePETROLEUM ENGINEER Date 07/31/2018 Approved By JACK SAVAGE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



P&A Procedure

BP America - Case B 21

Basin Fruitland Coal

1670' FNL & 1170' FEL, Section 18, T31N, R11W, San Juan County, NM API 30-045-27777

Plug & Abandonment Procedure:

- 1. Plug #1, 2872' 2922' (Fruitland top: 2444', Perfs: 2523' 2790'): RIH & set CICR at 2473".

 Pressure test tubing prior to pumping cement to 1000 psi. Mix & pump 6 sxs of Class B cement (or equivalent) to plug off Fruitland perfs. Sting out of CICR leaving 50' of cement on top of retainer. Circulate hole clean. If required run by BLM, run CBL (note: circulated cement to surface on primary cement job).
- 2. Plug #2, 976' 1181' (Ojo Alamo & Kirtland Tops: 1051'/ 1106'): Spot 23 sxs Class B cement in a balanced plug inside casing to cover Ojo Alamo and Kirtland tops. PUH. WOC. TIH to confirm top of plug. Re-spot if necessary.
- 3. Plug #4, (50' to Surface): Mix approximately 6 sxs of cement. Spot the surface plug to cover a minimum of 50' to surface and top off as necessary.
- 4. ND BOP and cut off wellhead below surface casing flange per regulation. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

CASE B 21

Proposed P&A

Basin Fruitland Coal 1670' FNL & 1170' FEL, Section 18, T31N, R11W, San Juan County, NM

> API 30-045-27777 Spud: 11/17/1990

Procedure Date: 1/3/2018

Surface Plug: 50' to Surface 6 sxs Class B

0 00

Hole Size: 12-1/4" Surface Csg: 8-5/8" 24# Hole Size: 7-7/8' Prod Csg: 5-1/2" 17#

1-1/4 tbg

8-5/8" Set @ 248' Cement w/ 250 sxs, circulated cmt to surf Circulated cmt to surf

Remedial Cement (1991): Perf at 620'

Ojo Alamo Top 1051'

PLUG 2: 976- 1181' 23 sxs Class B

Kirtland Top 1106'

Fruitland Top 2444' Fruitland Perfs: 2523- 2790'

Plug 1: 2423- 2473' Set CICR @ 2473'

6 sxs of class B

Pictured Cliffs Top: 2807'

PBTD: 2976' TD: 2992'

5- 1/2" csg set @ 2989' Cemented w/ 72 sxs & tail 200 sxs 2nd stage 370 sxs & tail 60 sxs Cement circ to surf

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Case B 21

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set Plug 1 (2473 2294) ft. to cover the Fruitland top. BLM picks top of Fruitland at 2344 ft.
 - b) Set Plug 2 (1223 976) ft. to cover the Kirtland top. BLM picks top of Kirtland at 1173 ft.
 - c) Set Surface Plug (298 0) ft. to cover the 8-5/8" casing shoe. Surface casing shoe at 248 ft.

Operator must run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

H₂S has not been reported in this section, however, high concentrations of H₂S (380 ppm GSV) and low concentrations of H₂S (21 ppm GSV) have been reported in Sec. 8, 31N, 11W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.