Form 3160-5 (June 2015) DI B			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMSF078615 6. If Indian, Allottee or Tribe Name		
	n. Use Ionn 5100-5 (AFI		broposais.				
SUBMIT IN TRIPLICATE - Other instructions on page 2					<ol> <li>If Unit or CA/Agreement, Name and/or No. 892000929B</li> </ol>		
1. Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: COAL BED METHANE					8. Well Name and No. NEBU 443A		
2. Name of Operator BP AMERICA PRODUCTION	ΊN		9. API Well No. 30-045-31354-00-S1				
3a. Address 380 AIRPORT RD DURANGO, CO 81303		3b. Phone No. (include area code) Ph: 281.892.5369			10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State				
Sec 24 T30N R8W SWNW 1780FNL 750FWL 36.799416 N Lat, 107.633553 W Lon			SAN JUAN CO		UNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize	Deepen		Production (Start/Resume)		U Water Shut-	-Off
	□ Alter Casing	🗖 Нус	lraulic Fracturing	🗖 Reclama	□ Reclamation		ity
Subsequent Report	Casing Repair		v Construction	□ Recomplete		□ Other	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	🖾 Plug	g and Abandon 🔲 Temporaril g Back 🔲 Water Disp		-		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation re- bandonment Notices must be fil-	give subsurface the Bond No. o sults in a multip	locations and measur n file with BLM/BIA le completion or reco	red and true ve . Required sub mpletion in a r	rtical depths of all pertin sequent reports must be ew interval, a Form 316	ent markers and zo filed within 30 day 50-4 must be filed on	nes. /s nce
BP requests to P&A the subje required reclamation plan doc	ct well. Please see the att	tached proce	dure, wellbore dia	agram, and	BLM		
In accordance with NMOCD F operations.	Pit Rule 19.15.17.9 NMAC	, BP will use	a closed-loop sys	stem during	NMOCD		
Notify NMOCD 24 hrs prior to beginning					AUG 2 0 2018		
		operat	tions	DI	STRICT II	1	
14. I hereby certify that the foregoing is	Electronic Submission #4 For BP AMERICA PR	ODUCTION C	OMPANY, sent to	the Farming	ton		
Committed to AFMSS for processing by JA Name (Printed/Typed) TOYA COLVIN			CK SAVAGE on 08/14/2018 (18JWS0180SE) Title REGULATORY ANALYST				
Signature (Electronic Submission)			Date 05/31/2018				
	THIS SPACE FO	DR FEDERA	L OR STATE	OFFICE US	SE		
						Date 08/1	14/2018
<u>Approved By</u> JACK SAVAGE Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			TitlePETROLEUM ENGINEER     Date 08/14/2018				
which would entitle the applicant to cond	act operations thereon.		Office Farming				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to ma	ke to any department or	agency of the Unite	2d
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED	D ** BLM RI	EVISED ** BLN	REVISED	** BLM REVISE	D **	

.

. •

2

NMOCD

#### PLUG AND ABANDONMENT PROCEDURE

May 28, 2018

### **NEBU #443A**

Basin Fruitland Coal 1780' FNL & 750' FWL, Section 24, T-30-N, R-8-W San Juan County, New Mexico / API 30-045-31354


- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.
  - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
    regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
    location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
    Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND
    wellhead and NU BOP. Function test BOP.
  - Rods: Yes\_\_\_\_, No\_\_X, Unknown\_\_\_\_. Tubing: Yes\_X, No\_\_\_, Unknown\_\_\_\_, Size <u>2 3/8"</u>, Length <u>3136'</u>.
     Packer: Yes\_\_\_\_, No\_X\_\_\_, Unknown\_\_\_\_, Type \_\_\_\_\_\_
  - 3. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
  - 4. Plug #1 (Fruitland perforations, top and 7" casing shoe, 3184' 2776'): Round trip 4 1/2" casing scraper or gauge ring to 2876' or deep as possible. RIH and set 4.5" CR at 2876'. Pressure test tubing to 1000#. Mix 65 sxs Class G cement; 47 sxs below CR and 18 sxs above. PUH and WOC. Tag and top off as necessary. PUH
  - Plug #2 (Kirtland and Ojo Alamo tops, 2349' 2192'): Circulate well clean. Pressure test casing to 800#. *If casing does not test then spot or tag subsequent plugs as appropriate.* Mix 40 sxs Class G cement inside casing from 2349' to 2192' to cover the Kirtland and Ojo Alamo tops. PUH.
  - Plug #3 (Nacimiento top, 1305' 1205'): Mix 29 sxs Class G cement inside casing from 1305' to 1205' to cover the Nacimiento top. PUH.
  - 7. Plug #4 (9-5/8" casing shoe, and surface, 388' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 75 sxs Class G cement and spot a balanced plug from 388' to surface, circulate good cement out casing valve. TOH and LD tubing. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface.
  - 8. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.

Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

# NEBU #443A

#### Proposed P&A Basin Fruitland Coal 1780' FNL & 750' FWL, Section 24, T-30-N, R-8-W San Juan County, NM, API #30-045-31354

Today's Date: **5/2418** Spud: 6/15/03 Completed: 7/31/03 Elevation: 6345' GL



TD @ 3256'

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: NEBU 443A

#### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

- 3. The following modifications to your plugging program are to be made:
  - a) Set Plug 3 (2294 2000) ft. to cover the Kirtland and Ojo Alamo tops. BLM picks top of Kirtland at 2244 ft. BLM picks top of Ojo Alamo at 2050 ft.
  - b) Set Plug 3 (890 790) ft. to cover the Nacmiento top. BLM picks top of Nacimiento at 840 ft.

Operator must provide CBL (2003) to verify cement top. Submit the electronic copy of the log for verification to the following addresses: <a href="mailto:jwsavage@blm.gov">jwsavage@blm.gov</a> Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.