Form 3160-5 (August 2007)

2.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

armington Child Off

NMSF078384

SUNDRY NOTICES AND REPO	ORISON WELLS	6. If Indian, Allottee of Tribe Name	
Do not use this form for proposals			
abandoned well. Use Form 3160-3 (A			
SUBMIT IN TRIPLICATE - Other instructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.	
Type of Well		The one of the proposition, a value and the control	
Oil Well X Gas Well Other		8. Well Name and No.	
		Newsom B 7N	
Name of Operator		9. API Well No.	
Hilcorp Energy Company		30-045-33880	
a. Address	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area	
382 Road 3100 Aztec, NM 87410	505-599-3400	Basin Dakota / Blanco Mesaverde	
Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		11. Country or Parish, State	
urface Unit F (SENW) 1620' FNL & 1900' FWL, Sec. 08, T26N, R08W		San Juan , New Mexico	
- *			

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other			
	Change Plans	Plug and Abandon	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	-			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.							

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota formation. Attached is the Mesaverde plat and procedure. A DHC application will be filed and approved prior to commingling. A Closed Loop system will be utilized.

SEE ATTACHED FOR

SFP 1 2 2018

Notify NMOCD 24 hrs prior to beginning operations BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

HOLD CTO4 FOR DHC

operations	HOLDS			
14. I hereby centify that the foregoing is true and correct. Name (Printed/Typed)				
Christine Brock	Title	Operations/	Regulatory Technician - Sr.	
Signature Christine Bruck	Date	9/10/2018		
THIS SPACE FOR FED	ERAL O	R STATE OF	FICE USE	
Approved by		Title	PE	Date 4/11/18
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which ventitle the applicant to conduct operations thereon.		Office	170	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Newsom B 7N

008-026N-008W-F

API: 3004533880

Mesa Verde Zone Add

09/07/2018

Proposed Procedure

- 1. MIRU Service rig and associated equipment
- 2. Test BOP's
- 3. TOOH with 2-3/8" tubing currently set with EOT at 6,556'
- 4. Set a CIBP @ 6,500' to isolate the Dakota. Set CIBP @ 4,700' to isolate MV frac.
- 5. Perforate and frac the Mesa Verde from 4,000' to 4,600' down a frac string. RDMO frac spread
- 6. MIRU Service rig
- 7. Test BOP's
- 8. PU mill & RIH to clean out to Dakota isolation plug
- 9. When water and sand rates are acceptable, flow test the Mesa Verde
- 10. Drill out Dakota isolation plug & TOOH
- 11. TIH and land production tubing. Obtain a commingled MV-Dakota flow rate
- 12. ND BOP's, NU production tree
- 13. RDMO service rig & turn well over to production

Hilcorp Energy Company

Current Schematic

Well Name: NEWSOM B #7N



