Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

DEC 17 2018

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010 BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NMSF078913 nton Field Office Farmin SUNDRY NOTICES AND REPORTS ON WELLS Bureau of 6.4f Indiana Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Lindrith B Unit Oil Well X Gas Well Other 8. Well Name and No. Lindrith B Unit 30 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-23859 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 West Lindrith Gallup/Dakota 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Unit I (NESE) 1680'FSL & 660' FEL, Sec. 16, T24N, R03W Surface Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Water Shut-Off Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other MIT Temporarily Abandon Change Plans Plug and Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company requests permission to perform an MIT on the subject well per the attached procedure and wellbore schematic. NMOCD JAN 3 1 2019 BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND DISTRICT 111 OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS Notify NMOCD 24 hrs prior to beginning operations 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr. Signature 12/17/2018 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter a within its jurisdiction.

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would



HILCORP ENERGY COMPANY LINDRITH B UNIT #30 Mechanical Integrity Test (MIT) Notice of Intent

JOB PROCEDURES

- 1. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 2. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Operations Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure (if any is present).
- 4. MIRU pump truck. Load the casing with 2% KCL water and corrosion inhibitor.
- 5. Perform Mechanical Integrity Test (MIT) by pressure testing the 5.5" casing above the bridge plug set @ 7,386' to 560 psig for 30 minutes on a 2 hour chart with a 1,000 lb spring.
- 6. If the test passes, shut in the well, RD pump truck, and move off of the location. If the test fails, contact the Operations Engineer.



HILCORP ENERGY COMPANY

LINDRITH B UNIT #30 Mechanical Integrity Test (MIT) Notice of Intent

