	Office	State of New Me	eX1CO	Form C-103
	District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013
	1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
	<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-045-11827
	<u>District III</u> – (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease STATE FEE
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
	1220 S. St. Francis Dr., Santa Fe, NM			FEE
Ī	87505 SUNDRY NOTI	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
		SALS TO DRILL OR TO DEEPEN OR PLU		7. Lease Name of Omit Agreement Name
		CATION FOR PERMIT" (FORM C-101) FO	OR SUCH	HUBBARD COM
	PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number
		ous wen		1
	2. Name of Operator	NIX/		9. OGRID Number
	HILCORP ENERGY COMPA 3. Address of Operator	N I		372171 10. Pool name or Wildcat
	382 Road 3100, Aztec, NM 874	110		Blanco Mesaverde/Basin Dakota
-	4. Well Location			
		feet from the South line	and 990	feet from the East line
	Section 25	Township 32N Ran		NMPM San Juan County
Ì	Section 25	11. Elevation (Show whether DR,	0	
1		637		
	12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data
			,	•
	NOTICE OF IN			SSEQUENT REPORT OF:
	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
	TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL		ILLING OPNS. P AND A
	PULL OR ALTER CASING ☐ DOWNHOLE COMMINGLE ☐	MULTIPLE COMPL	CASING/CEMEN	II JOB 🔲
	CLOSED-LOOP SYSTEM			
		RECOMPLETION	OTHER:	
				nd give pertinent dates, including estimated date
			C. For Multiple Co	impletions: Attach wellbore diagram of
	proposed completion or rec	ompletion.		
	Hilcorp Energy Company reque	sts permission to recomplete the sul	piect well in the Mo	esaverde and downhole commingle with the
				l plat. A DHC application will be filed and
	approved prior to commingling.	A closed loop system will be used.		
		Notif	NMOCD 24 hrs	NWOCD
	Density Exception Order	Approval R-14818 PF10	r to beginning	WIII-0-0-5
			perations	FEB 2 n 2019
•	KNotify OCD 24hrs prior	to MIT of the casing pric	00	1 20 20 2010
	to petacating			DISTRICT LII
	Spud Date:	Rig Release Da	to	and the same of th
1	Spud Date.	Kig Kelease Da	ic.	
-	I hereby certify that the information	above is true and complete to the be	est of my knowledg	ge and helief
	Thereby certify that the information	above is true and complete to the be	ost of my knowledg	ge and benefi.
		Q11		
1	SIGNATURE TUSULA	TITLE Operati	ons Regulatory Te	chnician Sr. DATE 2/19/2019
		<i>P</i>		PATONE TOTAL
	Type or print name Priscilla Sho	erty U E-mail address:	oshorty@hilcorp.co	om PHONE: 505-324-5188
	For State Use Only	1		
	APPROVED BY: 7266-10	TITLE \	3116	DUNIS DATE 2/21/19
	Conditions of Approval (if any):	Α.	· Comp	

District

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 263827

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-045-11827	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 319031	5. Property Name HUBBARD COM	6. Well No. 001
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6378

10. Surface Location

72					10.0	arrade Eddation	•				
	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
-	1	25	32N	12W		1650	S	990	E		SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Priscilla Shorty

Title: Operations Regulatory Technician - Sr.

Date: 2/15/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Robert Ernst

Date of Survey:

9/7/1966

Certificate Number:

2463



HILCORP ENERGY COMPANY HUBBARD COM 1 MESA VERDE RECOMPLETION SUNDRY

API#:

3004511827

JOB PROCEDURES

- 1. MIRU workover rig and associated equipment; NU and test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,620'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 7370' to isolate the Dakota
- 4. Load hole with fluid and run a CBL on the 4-1/2" casing. Verify cement bond within the Mesa Verde and confirm TOC. Review CBL results with the NMOCD and perform cmt remediation, as required. PT csg to 650 psi
- 5. Set a 4-1/2" cast iron bridge plug at +/- 5620' to provide a base for the frac.
- 6. Perforate the Mesa Verde. (Top perforation @ 4779', Bottom perforation @ 5570')
- 7. RIH w/ frac string and packer, set packer @ ~4725'. PT frac string to 9000#, PT backside to 300#.
- 8. Frac the Mesa Verde in 1 stage down frac string.
- 9. Flowback well until pressures diminish
- 10. MIRU workover rig. Nipple down frac stack, nipple up BOPs and test.
- 11. Release packer and POOH w/ frac string
- 12. TIH w/ mill and clean down to the top of the base of frac plug at 5620'. Take Mesa Verde gas samples and send for analysis
- 13. Drill out base of frac plug and cleanout to DK isolation plug at 7,370'. POOH.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 7,637'. TOOH.
- 15. TIH and land production tubing. ND BOPs and NU tree. Pump off expendable check.
- 16. RDMO. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY HUBBARD COM 1 MESA VERDE RECOMPLETION SUNDRY

