Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

OMB No. 1004-0137 Expires July 31, 2010

Well Integrity

Other

5. Lease Serial No. NMSF080669

6. If Indian, Allottee or Tribe Name

Reclamation

Temporarily Abandon

X Recomplete

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

Alter Casing

Casing Repair

Change Plans

	e this form for proposals well. Use Form 3160-3 (A		Tanagement of the control of the con			
SUI	BMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well			1			
Oil Well X	Gas Well Other	8. Well Name and No.				
			San Juan 27-4 Unit 47M			
2. Name of Operator			9. API Well No.			
	Hilcorp Energy Compa	any	30-039-26017			
3a. Address		3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area			
382 Road 3100, Aztec, N	M 87410	505-599-3400	Tapacito PC/Blanco MV/Basin DK			
4. Location of Well (Footage, Sec., T.,R	.,M., or Survey Description)		11. Country or Parish, State			
Surface Unit E (SV	VNW) 1580' FNL & 885' F\	NL, Sec. 20, T27N, R04W	Rio Arriba , New Mexico			
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	TICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION		TYPE OF AC	CTION			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume) Water Shut-Off			

Final Abandonment Notice Convert to Injection Plug Back Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Fracture Treat

New Construction

Plug and Abandon

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Mesaverde and Dakota. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.

Notify NMOCD 24 hrs prior to beginning operations

Subsequent Report

HOLD C104 FOR DHC-trimmingle



	01214151 111								
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)									
Etta Trujillo	Title	Operations/R	egulatory Technician	- Sr.					
Signature Ella Tyth	Date		2/22/20	019					
THIS SPACE FOR FED	ERAL C	R STATE OFF	ICE USE						
Approved by		Title	AT-M	Date 3/14/10					
Conditions of approval, if any, are attached. Approval of this notice does not warrant o that the applicant holds legal or equitable title to those rights in the subject lease which		Office		/					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



entitle the applicant to conduct operations thereon

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 263910

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-26017	2. Pool Code 85920	3. Pool Name TAPACITO PICTURED CLIFFS (PRO GAS)
4. Property Code 319210	5. Property Name SAN JUAN 27 4 UNIT	6. Well No. 047M
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6817


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
E	20	27N	04W		1580	N	885	W	RIO ARRIBA
						ł			

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres		13. Joint or Infill		14. Consolidation Code			15. Order No.		
320.00 W/2									

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

e: Operations/Regulatory Tech

Date: 02/18/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Neale C. Edwards

Date of Survey:

8/5/1998

Certificate Number:

6857



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 47M PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-3/8" tubing set at 8,000'.
- 3. Set a 4-1/2" plug at +/- 4,000' to isolate the Mesaverde formation and Dakota formation. Note: TOC at 3,164' by CBL.
- 4. Load the hole and pressure test the casing.
- 5. N/D BOP, N/U frac stack and pressure test frac stack.
- 6. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,699'; Bottom Perforation @ 3,770').
- 7. Isolate frac stage with a plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TiH with a mill and drill out top Pictured Cliffs isolation plug.
- 10. Clean out to Mesaverde formation and Dakota formation isolation plug.
- 11. Drill out Mesaverde formation and Dakota formation isolation plug and cleanout to PBTD of 8,104'. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota/Mesaverde/Pictured Cliffs flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 47M PICTURED CLIFFS RECOMPLETION SUNDRY

