Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMNM048576

Do not use the abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	7. If Unit or CA/Agreem	ent, Name and/or No.					
1. Type of Well ☐ Gas Well ☑ Oth	8. Well Name and No. FOOTHILLS C 1B						
Name of Operator HILCORP ENERGY COMPAN	Contact: M, NY E-Mail: mwalker@hile	KER (san juan nor		9. API Well No. 30-045-28974-00-S1			
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No Ph: 505.32	. (include area code) 4.5122		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, State			
Sec 19 T30N R12W NWNE 03 36.803452 N Lat, 108.133804			SAN JUAN COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	O INDICA	TE NATURE OF	NOTICE,	REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize ☐ De		pen	☐ Producti	on (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Recla		☐ Reclama	ation	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ Nev	New Construction ☐ Re		lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	☐ Plug and Abandon 🛮 Temp		arily Abandon		
BP	☐ Convert to Injection ☐ Plug Back ☐		☐ Water D	☐ Water Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi	ling estimated starting date of any proposed work and approximate duration thereof. locations and measured and true vertical depths of all pertinent markers and zones. In file with BLM/BIA. Required subsequent reports must be filed within 30 days le completion or recompletion in a new interval, a Form 3160-4 must be filed once requirements, including reclamation, have been completed and the operator has on the subject well per the attached NMOCD SEP 05 2019 DISTRICT III						
Electronic Submission #480038 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 09/03/2019 (19JK0159SE)							
Name (Printed/Typed) MANDI W	ALKER	Title OPERA	IONS REG	OLATORY TECH			
Signature (Electronic S	Date 08/22/2019						
	THIS SPACE FOR	FEDERA	L OR STATE C	OFFICE US	SE		
Approved By JOE KILLINS Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the a	TitleENGINEER Date 09/03/20 Office Farmington			Date 09/03/2019			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				villfully to ma	ke to any department or ago	ency of the United	

⁽Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





Hilcorp Energy Company FOOTHILLS C 1B

Temporarily Abandon API #: 3004528974

PROCEDURE

- 1. Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Property document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is property disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations.
- 2. MIRU service rig and associated equipment, ND casing risers
- 3. LOTO pumping unit, remove HH and bridle, PU on PR and unseat pump. POOH LD rods and pump.
- 4. ND tree and NU BOPs. Pressure and function test BOPs to 150/1500 psi.
- 5. PU on tbg, release hanger, scan and visually inspect tbg and POOH
- 6. PU junk mill and RIH to 1960', POOH LD junk mill
- 7. RIH w/ CBIP on tbg and set at 1825', PT CIBP and casing to 600 psi, POOH w/ setting tool.
- 8. RBIH w/ 250' of tbg to use as a kill string. NDNU tree verify tree and wellhead are equipped with functional pressure gauges. RDMO
- 9. Contact BLM and NMOCD to schedule witnessed MIT. PT csg to 600 psi.

