Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			Expires:	January 31, 2018	
			5. Lease Serial No. NMNM97843	5. Lease Serial No. NMNM97843	
			6. If Indian, Allottee	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agr	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well				8. Well Name and No. WF FEDERAL 28 4	
2. Name of Operator Contact: PRISCILLA SHOR			9. API Well No.		
HILCORP ENERGY COMPAN	com	30-045-30377-00-S1			
3a. Address 3b. Phone No. 1111 TRAVIS STREET Ph: 505-32 HOUSTON, TX 77002 Ph: 505-32		Phone No. (include area code) 505-324-5188	10. Field and Pool of HARPER HILL	 Field and Pool or Exploratory Area HARPER HILL 	
4. Location of Well (Footage, Sec., T		11. County or Parish, State			
Sec 28 T30N R14W SENW 18 36.787407 N Lat, 108.317147		SAN JUAN COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION		TYPE OF	TYPE OF ACTION		
S Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent ■ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	▼ Temporarily Abandon		
BK	☐ Convert to Injection	☐ Plug Back	■ Water Disposal	ter Disposal	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi Hilcorp Energy Company requ	rk will be performed or provide the Bo operations. If the operation results in pandonment Notices must be filed only inal inspection. Lests permission to temporarily in once gas prices rise. Please s	a multiple completion or record after all requirements, including abandon the subject well	mpletion in a new interval, a Form 31 ng reclamation, have been completed	60-4 must be filed once	
Notify NMOCD 24 hrs prior to beginning operations			NMOCD SEP 05 2019 DISTRICT III		
14. I hereby certify that the foregoing is	Electronic Submission #48004	Y COMPANY, sent to the	Farmington		
Name (Printed/Typed) PRISCILL	Title OPERA	Title OPERATIONS REGULATORY TECH			
Signature (Electronic S	Submission)	Date 08/22/20	Date 08/22/2019		
	THIS SPACE FOR FE	EDERAL OR STATE (OFFICE USE		
_Approved_By_JOHN_HOFFMAN			JM ENGINEER	Date 09/04/2019	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		et lease	Office Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





Hilcorp Energy Company WF FEDERAL 28-4

Temporarily Abandon API #: 3004530377

PROCEDURE

- 1. Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Properly document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is properly disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations
- 2. MIRU service rig and associated equipment, ND casing risers
- 3. LOTO pumping unit, remove HH and bridle, PU on PR and unseat pump. POOH LD rods and pump.
- 4. ND tree and NU BOPs. Pressure and function test BOPs to 150/1500 psi.
- 5. PU on tbg, release hanger, scan and visually inspect tbg and POOH
- 6. PU junk mill and RIH to 1115', POOH LD junk mill
- 7. RIH w/ CBIP on tbg and set at 1050', PT CIBP and casing to 600 psi, POOH w/ setting tool.
- 8. RBIH w/ 250' of tog to use as a kill string. NDNU tree verify tree and wellhead are equipped with functional pressure gauges. RDMO
- 9. Contact BLM and NMOCD to schedule witnessed MiT. PT csg to 600 psi.

