Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM024158		
Do not use th abandoned we	is form for proposals to drill II. Use form 3160-3 (APD) for	or to re-enter an r such proposals.	6. If Ir	ndian, Allottee or T	ribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.		
I. Type of Well ☐ Oil Well ⊠ Gas Well ☐ Oth	her			l Name and No. OCO A 2		
2. Name of Operator HILCORP ENERGY COMPAN	Contact: PRIS NY E-Mail: pshorty@hilcorp.	CILLA SHORTY com		Well No. 045-30643-00-	.C1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		Phone No. (include area code 505.324.5188	BA	eld and Pool or Ex SIN FRUITLAN ANCO PICTUR	ID COAL	
4. Location of Well (Footage, Sec., 7		11. County or Parish, State				
Sec 21 T30N R12W NWNW 6 36.803787 N Lat, 108.107715			SA	SAN JUAN COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	NDICATE NATURE C	F NOTICE, REPO	RT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent		Deepen	Production (Star	,	□ Water Shut-Off	
□ Subsequent Report	□ Alter Casing	Hydraulic Fracturing	Reclamation		 Well Integrity Other 	
☐ Final Abandonment Notice	□ Casing Repair □ Change Plans	 New Construction Plug and Abandon 	RecompleteTemporarily Ab		U Other	
	Convert to Injection	Plug Back	□ Water Disposal			
testing has been completed. Final Al determined that the site is ready for f Hilcorp Energy Company regu	l operations. If the operation results in bandonment Notices must be filed only inal inspection. Juests permission to temporarily n once gas prices rise. Please s	after all requirements, includ	ling reclamation, have b Il with the intent ure and	val, a Form 5160	the operator has	
	prio	y NMOCD 24 hrs r to beginning operations	NMO Sep d: Distric	5 2019		
	Electronic Submission #47733	Y COMPANY, sent to the sing by JOE KILLINS on (Farmington	SSE)		
Signature (Electronic S	Submission)	Date 08/09/2	019			
	THIS SPACE FOR FI	EDERAL OR STATE	OFFICE USE			
Approved By JOE KILLINS		TitleENGINEE	R		Date 08/29/2019	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivient which would entitle the applicant to condu-	uitable title to those rights in the subject	arrant or				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to any	for any person knowingly and matter within its jurisdiction	willfully to make to any	y department or ag	ency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED ** E				**	
					2	
		1.			3	



Hilcorp Energy Company Amoco A 2 Temporarily Abandon API #: 3004530643

RO	CEDURE
1.	Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Properly document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is properly disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations
2.	MIRU service rig and associated equipment, ND casing risers
3.	LOTO pumping unit, remove HH and bridle, PU on PR and unseat pump. POOH LD rods and pump.
4.	ND tree and NU BOPs. Pressure and function test BOPs to 150/1500 psi.
5.	PU on tbg, release hanger, scan and visually inspect tbg and POOH
5.	PU junk mill and RIH to 1800', POOH LD junk mill
7.	RIH w/ CBIP on tbg and set at 1775', PT CIBP and casing to 600 psi, POOH w/ setting tool.
8.	RBIH w/ 500' of tbg to use as a kill string. NDNU tree - verify tree and wellhead are equipped with functional pressure gauges. RDMO
9.	Contact BLM and NMOCD to schedule witnessed MIT. PT csg to 600 psi.

