Form 3160-5 (June ∠015)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

Lease Serial No.

NMSF079382

	,	, , , , , , , , , , , , , , , , , , , ,		
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. 891000538A			
Type of Well	8. Well Name and No. SAN JUAN 30-6 UNIT POW 1			
Name of Operator     HILCORP ENERGY COMPAN	9. API Well No. 30-039-24530-00-S1			
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		3b. Phone No. (include area code) Ph: 5053245161	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  Sec 24 T30N R7W SWNW 1485FNL 0795FWL 36.801220 N Lat, 107.527760 W Lon			11. County or Parish, State RIO ARRIBA COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOT	ICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			

☐ Water Shut-Off □ Acidize ☐ Deepen ☐ Production (Start/Resume) ■ Notice of Intent □ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ■ Well Integrity ☐ Subsequent Report Other □ Casing Repair ■ New Construction □ Recomplete ☐ Final Abandonment Notice □ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon ■ Water Disposal ☐ Convert to Injection ☐ Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy requests to perform pressure buildup testing on subject well per attached procedure and wellbore schematic.

NMOCD

SEP 3 0 2019

DISTRICT III

14. I hereby certify that the	ne foregoing is true and correct.  Electronic Submission #485497 verifie  For HILCORP ENERGY COMP  Committed to AFMSS for processing by JO	ANY, s	ent to the Farmington	
Name (Printed/Typed)	ETTA TRUJILLO	Title	OPERATIONS REGULATORY TECH SR	
Signature	(Electronic Submission)	Date	09/27/2019	
Signature	(Electronic Submission)	Date	09/2/1/2019	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
_Approved By_JQHN_HOFFMAN		TitleF	ETROLEUM ENGINEER	Date 09/30/201
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Farmington	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





# HILCORP ENERGY COMPANY SAN JUAN 30-6 UNIT 1 POW Fruitland Coal Layer Pressure Test SUNDRY

#### JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 2,833'.
- 3. RU wireline and make GR/JB run to veirfy perforation intervals are clear to set RBP's. Make GR correlation run to allow correlation on depth for setting RBP's.
- 4. Make GR/CCL correlation run to allow precise setting of RBP's between perforated intervals.
- 5. RIH w/ RBP and tandem DHPG's, set at 3,010'. Repeat process setting subsequent RBP's with tandem gauges at 2,986', 2,968', 2,966' and 2,842'. RD WI
- 6. RBIH w/ production tubing with RBP retrieving tool on end. ND BOP, NU and test WH.
- 7. RDMO rig while waiting 1-2 weeks for buildup data.
- 8. MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 9. Commence pulling RBP's with tubing.
- 10. RIH w/ production tubing and packer, set packer at 2,801' and land tubing.
- 11. Load the hole and perform MIT (Pressure test to 560 psi) in 2-3/8" tbg x 5-1/2" csg annulus above packer. Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 12. Ensure barriers are holding. ND BOP and BOP equipment.
- 13. RDMO location.



# HILCORP ENERGY COMPANY SAN JUAN 30-6 UNIT 1 POW Fruitland Coal Layer Pressure Test SUNDRY

