Form 3160-5 (June 2015)	UNITED STATES DEPARTMENT OF THE INTERIOR				FORM APPROVED OMB NO. 1004-0137		
BUREAU OF LAND MANAGEMENT					Expires: January 31, 2018 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					JIC106 6. If Indian, Allottee or Tribe Name		
					JICARILLA APACHE		
SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2		7. If Unit or CA/Agre	ement, Name and/or No.	
1. Type of Well					8. Well Name and No. JICARILLA B 1B		
Oil Well Gas Well Other					9. API Well No. 30-039-27780-00-C1		
HILCORP ENERGY COMPANY E-Mail: ettrujillo@hilcorp.com 3a. Address 3b. Phone No. (include					10. Field and Pool or		
382 ROAD 3100 AZTEC, NM 87410	Ph: 505-324-5161			BASIN DAKOTA BLANCO MESAVERDE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 26 T26N R4W SENE 228 36.458539 N Lat, 107.214765				RIO ARRIBA COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE	I , REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent	□ Acidize	Dee	pen	Produc	tion (Start/Resume)	□ Water Shut-Off	
	□ Alter Casing	🗖 Hyd	Iraulic Fracturing	□ Reclamation		Well Integrity	
			v Construction	Recomplete		Other Workover Operations	
☐ Final Abandonment Notice			g and Abandon g Back	 Temporarily Abandon Water Disposal 		in onkover operations	
Hilcorp Energy requests perm summary, current and propose work being performed.	ission to tri-mingle the sut ed wellbore schematic. Th	oject well acc le DHC (C-1	cording to the atta 07A) will be subm	ached hitted prior t	- 111	DIZIBICI OCL 1 1 50 NWOCD	
14. I hereby certify that the foregoing is	s true and correct.						
	Electronic Submission #4 For HILCORP EN	NERGY COM	ANY, sent to the	Rio Puerco			
Con Name (Printed/Typed) ETTA TRU	essing by JC	HN HOFFMAN on 10/11/2019 (20JH0004SE) Title OPERATIONS REGULATORY TECH SR					
		The OPERATIONS REC			BOLATORT TECHT		
Signature (Electronic S	Submission)		Date 10/10/20	019			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved Day 1011010000000			THEFTOOL			Deta 10/11/0010	
_Approved By_JQHN_HOFFMANConditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					LEK	Date 10/11/2019	
			Office Rio Puerco				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c	crime for any po to any matter w	erson knowingly and		ake to any department or	agency of the United	
Instructions on page 2)	ISED ** BLM REVISED	** BIM D		REVISE			
				REVISEL			
		I-Y					

	1
î	A
~	1
	1




HILCORP ENERGY COMPANY JICARILLA B 1B Trimingle Wellbore SUNDRY

1. Hilcorp Energy Company executed a routine tubing repair starting on 6/6/2019. Hilcorp MIRU and tripped out of the hole while scanning the tubing for integrity while tripping out. Hilcorp replaced 9 joints of tubing due to pitting. The next day Hilcorp tripped in the hole with a 3-7/8" bit, tagged fill @ 7,972, and cleaned out fill to 7,985' (PBTD). Hilcorp then picked up the tubing to 7,930' and spotted 250 gallons of acid across the DK perfs. Hilcorp picked up to 5,896' and spotted an additional 250 gallons of acid across the MV perfs. Hilcorp shut down for the day to let the acid breakdown the scale across the perfs. The next day Hilcorp tripped in the hole to 7,897' to unload the spent acid. Hilcrop tripped in the hole while unloading acid to 7,909', and began pressuring up on the air package. Hilcorp began tripping out of the hole and the tubing got stuck. At this point, it was unclear wh the tubing was stuck, and the bottom of the string (bit) was at 7,896'. Hilcorp RIH with a free point tool, and the free point tool would not go past 7,653'. Hilcorp chemical cut the tubing at 7,645'. The next day Hilcorp tripped out of the hole with 7,645' of the fish and tripped back in the hole with 3 3/4" wash pipe and tagged the top of fish at 7,645'. Hilcorp washed over the fish to 7,665' and began torquing up and getting metal shavings in the returns which indicated we were milling on casing. Hilcorp continued to attempt to wash over and did not make an inch in 3 hours and shut down for the day. The next day, Hilcorp tripped out of the hole with the 3-3/4" wash pipe, and tripped in the hole with a 3-3/4" overshot, 2-3/8" grapple, bumper sub and hydraulic jars. Hilcorp engaged the top of fish at 7,645' with the overshot/grapple assembly and jarred on the fish. Hilcorp tripped out of the hole and recovered a 10' piece of fish. The bottom of the fish was crimped (indicating collapsed casing). At this point, Hilcorp had attempted to fish the tubing with washpipe and an overshot assembly with very little success. Hilcorp believes there is no viable option to fish the remaining fish out of the hole based on the condition of the casing. Hilcorp has verified collapsed casing from 7,655'-7,665', which is in the Greenhom (a sub member of the Mancos). Hilcorp was granted approval to land the end of tubing at 7,629' (26' above the top of fish) and shut in the well to wait for DHC approval. The Greenhorn is a calcareous, deep water, shale deposit with extremely low permeability and no sand quality. In the 9 section area around the Jicarilla B 1B, there has only been one well completed in the Greenhorn, the Jicarilla F 1. The Greenhorn was perforated, fractured, and further acidize, before being squeezed off with cement due to the lack of productivity. The Greenhorn interval never produced. Based on this information, Hilcorp wishes to trimingle the Mesaverde, Mancos, and Dakota formations and allocate 0 production to the Greenhorn (Mancos) due to the lack of productivity of the Greenhorn in the area. Hilcorp has gotten approval from both BLM and Jicarilla to proceed to submit the DHC with 0 production allocated to the Mancos. Hilcorp has notified interest owners in the Mesaverde, Mancos, and Dakota formations with the proposition to trimingle the formations and allocate 0 production to the Mancos, and is currently waiting for partner approval.



-14

HILCORP ENERGY COMPANY JICARILLA B 1B Trimingle Wellbore SUNDRY





- +

HILCORP ENERGY COMPANY JICARILLA B 1B Trimingle Wellbore SUNDRY

