Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY	5. Lease Serial No. NMNM101552							
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name							
SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well ☐ Oil Well	8. Well Name and No. WF FEDERAL 1 1							
Name of Operator HILCORP ENERGY COMPAN	9. API Well No. 30-045-30660-00-S1							
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505-324-5188		10. Field and Pool or Exploratory Area HARPER HILL					
4. Location of Well (Footage, Sec., T.		11. County or Parish, State						
Sec 1 T30N R14W NESW 194 36.841011 N Lat, 108.264197	SAN JUAN COUNTY, NM							
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION							
☑ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation		■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete		☐ Other			
☐ Final Abandonment Notice	□ Change Plans	□ Plug and Abandon	▼ Temporarily Abandon					
BP	☐ Convert to Injection	☐ Plug Back	☐ Water D	Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Hilcorp Energy Company requests permission to temporarily abandon the subject well with the intent to return the well to production once gas prices rise. Please see the attached procedure and wellbore schematic.								
				APRIL OF THE PARTY.	ALLOW AND A STATE OF THE ALLOW AND A STATE OF			

Notify NMOCD 24 hrs prior to beginning

operations

NMOCD

SEP 05 2019

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Electronic Submission #477514 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by JCHN HOFFMAN on 09/03/2019 (19JH0146SE)							
Name (Printed/Typed) PRISCILLA SHORTY Title OPER		PERATIONS REGULATORY TECH					
Signature	(Electronic Submission) THIS SPACE FOR FEDERA	Date	08/12/2019 STATE OFFICE USE				
_Approved_By_JOHN HOFFMANConditions of approval, if any, are attached. Approval of this notice does not warrant or		TitlePETROLEUM ENGINEER		Date 09/03/2019			
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United							

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





Hilcorp Energy Company WF FEDERAL 1-1

Temporarily Abandon API #: 3004530660

PROCEDURE

- 1. Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Properly document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is properly disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations
- 2. MIRU service rig and associated equipment, ND casing risers
- 3. LOTO pumping unit, remove HH and bridle, PU on PR and unseat pump. POOH LD rods and pump.
- 4. ND tree and NU BOPs. Pressure and function test BOPs to 150/1500 psi.
- 5. PU on tbg, release hanger, scan and visually inspect tbg and POOH
- 6. PU junk mill and RIH to 1550', POOH LD junk mill
- 7. RIH w/ CBIP on tbg and set at 1475', PT CIBP and casing to 600 psi, POOH w/ setting tool.
- 8. RBIH w/ 250' of tbg to use as a kill string. NDNU tree verify tree and wellhead are equipped with functional pressure gauges. RDMO
- 9. Contact BLM and NMOCD to schedule witnessed MIT. PT csg to 600 psi.

