Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMSF078905

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	ŝ.

ERN NAV	e	
	 	_

	EASTERN NAVAJO		
SUBMIT IN TRIPLICATE - Other instr	7. If Unit or CA/Agreement, Name and/or No. 892000844F		
Type of Well Oil Well		8. Well Name and No. GALLEGOS CANYON UNIT 217E	
Name of Operator Contact: PATTI CAMPBELL BP AMERICA PRODUCTION CO E-Mail: patti.campbell@bpx.com		9. API Well No. 30-045-24645-00-C1	
3a. Address 1199 MAIN AVE SUITE 101 DURANGO, CO 81301	3b. Phone No. (include area code) Ph: 970-712-5997	Field and Pool or Exploratory Area BASIN DAKOTA PINON GALLUP	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State		
Sec 13 T28N R12W NWNW 0840FNL 1050FWL 36.667010 N Lat, 108.067950 W Lon		SAN JUAN COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			

TYPE OF SUBMISSION	TYPE OF ACTION			
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	 □ Deepen □ Hydraulic Fracturing □ New Construction ➡ Plug and Abandon □ Plug Back 	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity ☑ Other ☑ H □ Par

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BP believes the bradenhead issue with the referenced well is a wellhead issue. To investigate the issue, BP will run a CBL and pressure test the casing to eliminate any uncertainty regarding the source of the pressure. Please reference the attached procedure.



which would entitle the applicant to conduct operations thereon.

DISTRICT 111

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #495958 verifie For BP AMERICA PRODUCTIO Committed to AFMSS for processing by JO	N CO.	sent to the Farmington	
Name (Printed/Typed)	PATTI CAMPBELL	Title	REGULATORY ANALYST	
Signature	(Electronic Submission)	Date	12/16/2019	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By JOHN H	OFFMAN	TitleP	ETROLEUM ENGINEER	Date 12/17/2019
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease			-	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office Farmington

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



GCU 217E

840 FNL & 1050 FWL, Section 13, T28N, R12W San Juan County, NM / API 3004524645

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.
- 2. Check casing, tubing, and bradenhead pressures.
- 3. Removed existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOP. Function test BOP.
- 5. P/U 5 1/2" plug, TIH and set at 5370'. Load hole, and pressure test casing to 800 psi. POOH w/ tubing.
- 6. RU wireline and run CBL with 500 psi on casing from plug to surface to identify TOC. Adjust plugs as necessary for new TOC. Email log copy to John Hoffman (BLM) at ihoffman@blm.gov and Brandon Powell at Brandon.powell@state.nm.us upon completion of logging operations.
- 7. If CBL and pressure test are good, proceed with wellhead repair. Otherwise, rig down and return later for P&A.
- 8. Swap out wellhead.
- 9. RIH and retrieve plug.
- 10. RIH w/ tubing and land EOT @ 6120'.
- 11. ND BOP and NU wellhead.
- 12. RIH w/rod string. RDMO



GCU 217E GP/DK API # 30-045-24645 Unit D - Sec. 13 - T28N - R12W San Juan, NM

Formation Tops

Tormation rops	
Kirtland	Surface
Fruitland	1125
Pictured Cliffs	1450
Lewis	1535
Cliff House	3000
Menefee	3130
Point Lookout	3890
Mancos	4200
Gallup	5090
Greenhorn	5840
Graneros-Dakota	5950
Dakota	6018

Deviation Survey

Deviation Survey		
Depth	Inclination	
329	0.25	
839	0.50	
1328	0.50	
1857	0.75	
2352	0.75	
2845	0.75	
3342	1.00	
3830	0.75	
4304	1.00	
4835	1.00	
5331	1.25	
5819	1.00	
6187	1.50	

Gallup Perforations
5420' - 5620' 2 spf, 0.44"

Frac'd w/ 126k gal frac fluid & 190k# 20/40

Dakota Perforations

Duitota i ci	OI attions
5950' - 5959	
5964' - 5970	2 spf, 0.44"
6018' - 6050	2 spf, 0.44"
6054' - 6057	' 2 spf, 0.44"
6059' - 6066	' 2 spf, 0.44"
6070' - 6080	' 2 spf, 0.44"
Frac'd w/ 10	0k gal frac fluid & 125k# 20/40

12' KB GL: 5541'

