Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. NMSF080673

_				
	If Indian.	Allottee	or Tribe	Name

abandoned well. Use form 3160-3 (API	o. If Indian, Affolice of The Name		
SUBMIT IN TRIPLICATE - Other inst	7. If Unit or CA/Agreement, Name and/or No. 8910010540		
1. Type of Well	8. Well Name and No. SAN JUAN 27-4 UNIT 42		
☐ Oil Well Gas Well Other		0/11/00/11/27 4 01(1) 42	
Name of Operator Contact: TAMMY JONES HILCORP ENERGY COMPANY E-Mail: tajones@hilcorp.com		9. API Well No. 30-039-20132-00-S1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	3b. Phone No. (include area code) Ph: 505.324.5185	10. Field and Pool or Exploratory Area BASIN DAKOTA	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description,	11. County or Parish, State		
Sec 8 T27N R4W NESW 1500FSL 1550FWL 36.584442 N Lat, 107.276794 W Lon	RIO ARRIBA COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			

TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent ■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	■ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
BP	☐ Convert to Injection	☐ Plug Back	□ Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure, wellbore schematic & gas capture plan. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities.

NMOCD

JAN 10 2020

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Electronic Submission #491618 verified by the BLM Well Information System For HILCORP ENERGY COMPANY, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 11/13/2019 (20JK0051SE)					
Name (Printed/Typed)	TAMMY JONES	Title	REGUALATORY SPECIALIST		
Signature	(Electronic Submission)	Date	11/08/2019		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
_Approved By_JOE KIL	LI <u>N</u> S	Title	NGINEER		Date 01/07/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	· Farmington		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United			cy of the United		

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. SI Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

Section

UL - Lot

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 274036


WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-20132	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Weil No.
319210	SAN JUAN 27 4 UNIT	042
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6711

Township Range O4W Lot Idn Feet From N/S Line Feet From E/W Line County RIO ARRIBA

11. Bottom Hole Location If Different From Surface EW Line UL - Lot Section Township Range Lot Idn Feet From N/S Line Feet From County 14. Consolidation Code 15. Order No. 12. Dedicated Acres 13. Joint or Infill 320.00

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION






HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 42 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP. Check bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM of any anomalous pressure changes.
- 2. TOOH with 2-3/8" tubing set at 7,974'.
- 3. Set a 4-1/2" plug at +/- 7,744' to isolate the Dakota.
- 4. Load the hole and perform MIT (Pressure test to 560 psi). Notifiy NMOCD and BLM +/-24hr prior to testing (and in the event of a failed test).
- 5. RU W/L, run CBL, record TOC.
- 6. Set a 4-1/2" plug at +/- 6,300'.
- 7. Load the hole and pressure test the casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesaverde formation (Top Perforation @ 5,200'; Bottom Perforation @ 6,150').
- 10. If needed, isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out any plugs above the Dakota isolation plug.
- 13. Clean out to Dakota isolation plug.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 7,996'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Mesaverde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 42 MESA VERDE RECOMPLETION SUNDRY



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

CONDITIONS OF APPROVAL

- 1. Farmington Office is to be notified at least 24 hours before the operations commence (505) 564-7750.
- 2. Submit electronic copy of the CBL for verification to the following addresses: jkillins@blm.gov and Brandon.Powell@state.nm.us. Based on CBL results inside/outside plugs and volumes will be adjusted accordingly. Please review the General Requirements document to ensure volumes meet required excess inside and outside casing.