Form 3160-5 (June 2015)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	N00C14205579

6	If Indian,	Allottee	or Tribe	Nam
U.	FACTE			1 vaiii

abandoned wel			6. If Indian, Allottee EASTERN NAV		С			
SUBMIT IN 1	page 2		7. If Unit or CA/Agro	eement, Name	and/or No.			
Type of Well	ner				8. Well Name and No. POLLY TURPIN 1			
Name of Operator     DJR OPERATING LLC	Contact: A E-Mail: amascarena	ALICE MASC as@djrllc.com	ARENAS		9. API Well No. 30-045-26312-00-S1			
3a. Address 1 ROAD 3263 AZTEC, NM 87410		3b. Phone No. Ph: 505-63	(include area cod 2-3476	c)	Field and Pool or Exploratory Area     BISTI			
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County or Parish, State			
Sec 27 T25N R12W NWNE 06 36.377533 N Lat, 108.096008					SAN JUAN COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE (	OF NOTICE,	REPORT, OR OT	HER DAT	A	
TYPE OF SUBMISSION			ТҮРЕ С	OF ACTION				
Notice of Intent	☐ Acidize	☐ Deep	en	☐ Product	ion (Start/Resume)	☐ Wate	r Shut-Off	
. (	☐ Alter Casing	☐ Hydi	raulic Fracturing	Reclam	ation	☐ Well	Integrity	
☐ Subsequent Report	☐ Casing Repair	New	Construction	□ Recomp	olete	Other		
Final Abandonment Notice	☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon		arily Abandon	Final Abandonmentice				
6	☐ Convert to Injection	Plug	Back	☐ Water I	Disposal			
DJR Operating, LLC requests been plugged and abandoned #1 was conducted with FFO-B determined because this well 1R, API 30-045-310043, B-Se prudent to wait till the DJR Bis reclamation for the entire local	final inspection.  final abandonment approving the following reason: BLM AO Randy McKee and is on a twinned location with the following the control of the following the control of the following the	oject well, after 18 an on-site o an of DJR Ope perating, LLC L, San Juan C	the well has f the Polly Tuerating, LLC. Bisti Coal 27 o., NM. It wo	Irpin It was Com uld be	NMO DEC 17	CD 2019		
14. I hereby certify that the foregoing is  Committee	Electronic Submission #4 For DJR OPE ted to AFMSS for processin	95537 verified RATING LLC g by ALBERT	by the BLM Way sent to the Fa A WETHINGTO	ell Information Irmington N on 12/13/201	1 System 19 (20AMW0024SE)			
	ASCARENAS			LATORY TE				
Signature (Electronic S	Submission)		Date 12/12/	2019				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE			
_Approved By_SARAH SCOTT Conditions of approval, if any, are attache	TitleSUPERV	ISORY NATU	JRAL RESOURCE	SPECIAPato	: 12/16/20			
certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the act operations thereon.	subject lease	Office Farmin					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any department or	agency of th	e United	

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*















# DJR Plug & Abandon Procedure November 7, 2019

Well:

**POLLY TURPIN #001** 

API: Field: 30-045-26312

Location:

660' FNL & 1980' FEL

Gallup

Sec,T, R:

Sec 27, 25N, 12W

Elevation:

GL: 6338'

Cnty/State: San Juan, New Mexico

Lat/Long:

36.29136,-108.0966492

By:

Aztec Well Servicing

#### Objective:

Permanently plug & abandon the well from 4945' to surface containing 5 cement plugs.

### Note:

All cement volumes use 100% excess outside casing and 50' excess inside pipe. Stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class G neat yield or equivalent. If casing pressure tests tagging plugs will not be required.

### Prior to Rig:

- 1. Notify BLM & NMOCD
- 2. Note: verify all cement volumes based on actual slurry to be pumped.
- 3. See attached COA's from BLM & NMOCD.

#### Procedure:

- MIRU well servicing rig and cement equipment.
- 2. Check casing, tubing, and bradenhead pressures.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. LD rods.
- 5. ND wellhead and NU BOP. Function test BOP. RU floor and 2-3/8" handling tools.
- LD production tubing.
- 7. PU casing scraper, tally RIH with 2-3/8" workstring to 4750'.
- 8. TOOH and LD casing scraper.
- 9. TIH with 5-1/2" CR and set @ 4738'.
- 10. Pressure test tubing to 1000psi then sting out CR. Load hole, and pressure test casing to 500 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. WOC to be determined on pressure test.
- 11. TOOH.
- 12. RU WL and run CBL. RD WL.
- 13. TIH open ended to 4738'.
- 14. Plug 1: 4738' 4552' (Gallup perfs & top: 4602') Mix 28 sacks Class G cement and spot a balanced plug on top of CR to cover the perfs and Gallup top. PU and reverse circulate tubing clean.















# DJR Plug & Abandon Procedure November 7, 2019

Well:

POLLY TURPIN #001

API: Field: 30-045-26312

Location:

660' FNL & 1980' FEL

Gallup

Sec.T. R:

Sec 27, 25N, 12W

Elevation:

GL: 6338'

Cnty/State: San Juan, New Mexico

Lat/Long:

36.29136,-108.0966492

By:

Aztec Well Servicing

- 15. LD tubing to 3730'.
- 16. Plug 2: 3730' 3630' (Mancos top: 3680') Mix 18 sacks Class G cement and spot a balanced plug to cover the Mancos formation top. PU and reverse circulate tubing clean.
- 17. LD tubing to 1474'.
- 18. Plug 3: 1474' 1374' (Mesaverde top: 1424') Mix 18 sacks Class G cement and spot a balanced plug to cover the Mesaverde top. PU and reverse circulate tubing clean.
- 19. LD tubing to 1144'.
- 20. Plug 4: 1144' 1044' (Pictured Cliff top: 1094') Mix 18 sacks Class G cement and spot a balanced plug to cover the Pictured Cliff top. PU and reverse circulate tubing clean.
- 21. LD rest of tubing.
- 22. RU WL and perforate at 330'. RD WL.
- 23. Plug 5: 330' 0' (Casing shoe: 280') Establish circulation out BH with water. Mix approximately 104 sacks Class G cement (39 sxs inside 65 sxs outside) and pump down casing and out BH until good cement returns to surface.
- 24. ND BOP and cut off wellhead below surface casing flange per regulation. Top off w/cement if needed. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.















# DJR Plug & Abandon Procedure November 7, 2019

Well: Location: Sec,T, R:

POLLY TURPIN #001 660' FNL & 1980' FEL

Sec 27, 25N, 12W

Cnty/State: Lat/Long:

San Juan, New Mexico 36.29136,-108.0966492 API: Field: 30-045-26312

Gallup

Elevation: GL: 6338'

By:

Aztec Well Servicing

# **POLLY TURPIN #001**

Proposed P&A Gallup

API 30-045-26312

Plug 5: 330' - 0' 104 sxs, class G

Pictured Cliff top @ 1094'

Plug 4: 1144' - 1044'

18 sxs, class G

Mesaverde top @ 1424'

Plug 3: 1447' - 1374'

18 sxs, class G

Mancus top @ 3680'

Plug 2: 3730' - 3630' 18 sxs, class G

Gallup top @ 4602'

Plug 1: 4738' 4552' 28 sxs, class G CICR @ 4738'

12-1/4" hole Surface Casing 8-5/8" 24# Set @ 280' 150 sxs, cement Perf @ 330'

TOC: 857' (calculated)

Perfs @ 4796' - 4606'

7-7/8" hole 5-1/2" 15.5# casing set @ 4943' cemented w 400sxs + 200sxs

TD: 4945'

