

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Larry Schlotterback
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name Riddle F LS 5	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No NMNM073382
---------------------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter A	Section 32	Township 28N	Range 08W	Feet from the 790	North Line	Feet from the 1090	East Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	------------	------------------------------	-----------	---------------------------

Latitude 36.62287788 Longitude -107.6989485

NATURE OF RELEASE

Type of Release: Condensate	Volume of Release 5.5 bbls	Volume Recovered 0
Source of Release: Tank Manway	Date and Hour of Occurrence: Unkown	Date and Hour of Discovery 5/17/07 14:20
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM & NMOCD	
By Whom? Larry Schlotterback	Date and Hour: 5/18/07 - 9:00 am	RCVD JUN 7 '07
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	



DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During a scheduled gauging of the stock tank, the gauger noticed a stained area around the manway. Upon further inspection he found a leaking manway. Manway bolts were found loose. The gauger immediately tightened the loose bolts and stopped the leak. BP San Juan Team Leader ordered the well to be shut-in and an investigation.

Describe Area Affected and Cleanup Action Taken.* All fluids remained in secondary containment. The impacted soil will be cleaned up and taken to our Crouch Mesa Land Farm. Other vessels with similar manway designs and/or construction dates will be inspected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Schlotterback	Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator	Approval Date: 6-7-07	Expiration Date:
E-mail Address: schlln@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/4/07	Phone: 505-326-9425	

* Attach Additional Sheets If Necessary

BP0719442286