NO. OF OPIES RE	CEIVED 3				Form C-103
DISTRIBUT	ION				Supersedes Old
SANTA FE	/ / /	NEW MEXICO OIL O	CONSERVATION COMMISSION	N	C-102 and C-103 Effective 1-1-65
FILE	1				
U.S.G.S.					5a. Indicate Type of Lease
LAND OFFICE					State Fee. XX
OPERATOR	/		•		5. State Oil & Gas Lease No.
	· .				
(DO NOT U	SUNDR SE THIS FORM FOR PRO USE "APPLICATI				
014 (737)	GAS [				7. Unit Agreement Name
WELL XX	WELL L	OTHER-			Hospah Sand Unit
2. Name of Operato		_			8. Farm or Lease Name
	Petroleum Cor	poration			
3. Address of Oper			70200		9. Well No.
		vard, San Antonio, Te	exas /8209		8
4. Location of Well					10. Field and Pool, or Wildcat
UNIT LETTER _	<u>K</u> 2	310 FEET FROM THE SOU	ith Line and 2310	FEET FROM	Hospah
THE Wes	3.1	on 1 township 1	L7N PANCE 9W	NAGA	
105105	ZINE, SECTION	15. Elevation (Show wh		NIVIE WIT	
			12. County McKinley		
16.	Chack	6928' GL Appropriate Box To Indica	te Nature of Notice Re	port or Oth	per Data
	NOTICE OF IN			-	REPORT OF:
PERFORM REMEDIA	WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABAN	DON	÷	COMMENCE DRILLING OPNS	·	PLUG AND ABANDONMENT X
PULL OR ALTER CAS	SING	CHANGE PLANS	CASING TEST AND CEMENT		L3
			OTHER	<del></del>	
OTHER			- []		
17. Describe Propo work) SEE RU		erations (Clearly state all pertinen	nt details, and give pertinent dat	tes, including	estimated date of starting any proposed
7-27-69:	Set plug in	bottom from 1450' to	1540' with 30 sack	s cement	plus 2% CaCl.
8-4-69:	Perforated v	with 4 shots at 570' common plus 2% CaCl.	GL. Bradenhead sque Top of cement insid	ezed p <b>er</b> le 7" tag	forations with ged at 300'.
8-7-69:	Set 5-sack p	plug in top of 7".			on hing.
1-27-70:	Set 2-sack	plug and marker at su	rface.	F	
Cleaned a	and leveled lo	ocation with bulldoze	r.	J	UL 1 1970
			1 /	012	DIST. 3

## NEW MEXICO OIL CONSERVATION COMMISSION 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

Tesoro Petroleum Corp 8520 Crown hill Blud San Antonio, Texas 98109 Re: Plugging Reports



Gentlemen:

Form C-103, Notice of Intention to Plug, your Hospa 4

K - 1 - 17N - 9W was approved 7 - 28 - 69

Your

subsequent notice of plugging cannot be approved until a commission representative has made an inspection of the location to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

Fill in below and return:

Hospah Unit

1-17N-9W is ready for your inspection and Well 8

approval.

Santa Fe

Lease

TESORO PETROLEUM CORPORATION

Operator

Name and

UL 3-270

NO. OF COPIES RECEIVED	3	•		Form C-103
DISTRIBUTION				Supersedes Old
SANTA FE	1		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	1	-		2.1351.76 11 05
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State Fee. XX
OPERATOR	1			5. State Oil & Gas Lease No.
(DO NOT USE THIS F	SU ORM FO	NDR'	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1.				7. Unit Agreement Name
OIL GAS			OTHER-	Hospah
2. Name of Operator	8. Farm or Lease Name			
Tesoro Petrole	um C	orpo	ration	
3. Address of Operator	9. Well No.			
8520 Crownhill	8			
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER K		23	10 FEET FROM THE South LINE AND 2310 FEET FROM	Hospah
THE West	LINE, S	SECTIO	TOWNSHIP 17N RANGE 9W NMPM.	
			15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		7777	0350. <b>(%)</b>	McKinley
16.	Che	ck A	ppropriate Box To Indicate Nature of Notice, Report or Otl	her Data
NOTI				T REPORT OF:
PERFORM REMEDIAL WORK			PLUG AND ABANDON XX REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS CASING TEST AND CEMENT JOB	
			OTHER	
OTHER				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Propose the following work to plug and abandon: Place 100' cement plug in bottom; go in with tubing and set Guiberson GW cup packer with cup looking up; pressure annulus to check for casing leaks; if casing holds, perforate with 4 ring shots at approximately 570'; mix 75 sacks cement and displace with conventional plug method to approximately 300', this depth to be determined by wireline check; if casing does not hold when pressure tested, run cast iron retainer and set at 300' after perforating as above; mix 75 sacks cement and displace tubing. Place 5-sack plug in top of pipe with marker as per State requirements.

plug in top of pipe with marker as per St	tate requirements.	
		RECEIVED
		JUL 28 1969 CIL CON. COM. DIST. 3
18. I hereby certify that the information above is true and complete to the best	of my knowledge and belief.	
SIGNED Harold Vaylborg TITLE	Vice President	July 22, 1969
APPROVED BY LILLUY (UNLY TITLE CONDITIONS OF APPROVAL, FF ANY:	Sup Part 111	DATE 7-28-69