



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan Co
Lease No. 973478
Unit Undesignated

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 20, 1960

Well No. 3-4-7 is located 300 ft. from SN line and 300 ft. from EW line of sec. 7

23-23-23 Sec. 7 12N 30W N.T.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Holladay New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6067 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plans to drill this previously approved test with cable tools have been abandoned due to time element. Now propose to drill 2000' diameter test with rotary rig. Drill surface hole, cement 1 - 2 joints of surface casing. Drill to and test diameter formation. Run and cement production casing, or plug and abandon, as the case may be. Well location and average dedication plot previously submitted and approved.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SANDEE MINING COMPANY

Address Suite 1500
1700 Broadway
Denver 2, Colorado

By A. E. Woodley
A. E. Woodley
Title Land Dept

Faint, illegible text, possibly bleed-through from the reverse side of the page. The text is arranged in several paragraphs and is mostly illegible due to low contrast and blurriness.



Faint, illegible text at the bottom of the page, possibly bleed-through or a footer. The text is mostly illegible due to low contrast and blurriness.