

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐

OTHER

Injection well

2. Name of Operator

American Exploration Company

3. Address of Operator

P.O. Box 10509, Midland, TX 79702

4. Well Location

Unit Letter EF: 1335 Feet From The North Line and 1325 Feet From The West Line

Section

7

Township

17N

Range

8W

NMFM

McKinley

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A.

1. MURK WOP.

2. Circ. hole w/9.0 ppg mud. OMIT

3. Spot cmt plug 1592' - 1392' (per P's 1564 - 1589').

4. Spot cmt plug 200' - surface AMEND

5. Install P&A marker.

RECEIVED

JUN -1 1992

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Dennard

TITLE Engineer

TYPE OR PRINT NAME David Dennard

OIL CON. DIV.
DISTRICT II

DATE 6/1/92

TELEPHONE NO. 687-0587

(This space for State Use)

APPROVED BY Severna J. Juchacz

TITLE

DEPUTY OIL & GAS INSPECTOR

DATE 6/1/92

CONDITIONS OF APPROVAL, IF ANY:

OMIT STEP 2. AMEND STEP 4 - PERFORATE 4 1/2" CSG AT 200' AND CIRCULATE CMT TO SURFACE IN BRADENHEAD. LEAVE 4 1/2" CSG FULL OF CMT TO SURFACE. IF PLUG NOT IN PLACE, FILL TO 1392'.