

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <i>Saguaro Oil Company</i>	8. Farm or Lease Name <i>Jenneco-Santa Fe RR</i>
3. Address of Operator <i>P. O. Box 51, Farmington, New Mexico 87401</i>	9. Well No. <i>1</i>
4. Location of Well UNIT LETTER <i>330</i> FEET FROM THE <i>West</i> LINE AND <i>990</i> FEET FROM THE <i>North</i> LINE, SECTION <i>31</i> TOWNSHIP <i>18N</i> RANGE <i>8W</i> NMPM.	10. Field and Pool, or Wildcat <i>N. E. Hospah</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>7094 GL</i>	12. County <i>McKinley</i>

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval to plug and abandon well was secured from Mr. Emery Arnold on or about 6-5-75 as follows:

# 1	0' - 10'	3 AX	in surface casing point lookout open hole Gallup-Hospah open hole
# 2	700' - 850'	23 AX	
# 3	1650' - 1930'	44 AX	

Plugs to be set through 2 3/8" drill pipe.

Rig down and move all equipment from location.

Clean and Level Location.

Set dry hole marker.

Work to be completed before 6/30/75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Ben Nelson* TITLE *Spt.* DATE *3-17-78*

APPROVED BY *AR Kendrick* TITLE *SUPERVISOR DIST. #3* DATE *MAR. 22 1978*

CONDITIONS OF APPROVAL, IF ANY: