

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BC&D Oil and Gas Corporation

3. Address and Telephone No.

PO Box 837, Hobbs NM 88241 (505) 397-3972

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL, 2460' FWL, Sec. 6, T17N, R8W

5. Lease Designation and Serial No.

NM 052931

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hanson 33

9. API Well No.

30-031-20450

10. Field and Pool, or Exploratory Area

Hospah Lower Sand South

11. County or Parish, State

McKinley, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

BC&D Oil and Gas request permission to plug and abandon subject well by following the attached procedure.

8 5/8" 24# Csg. @ 103' with cement circulated  
5 1/2" 14# Csg. @ 1644' with 100 sx cmt (TOC @ 1030')  
Perf. @ 1519' - 1550'  
CIBP @ 1478'

Formation Tops:

Point Look Out 282'  
Mancos Shale 503'  
Hosta 823'  
Hospah 1521'

RECEIVED  
APR 11 1997  
OIL CON. DIV.  
DIST. 3

RECEIVED  
BLM  
97 MAR 12 AM 11:16  
070 WASHINGTON, NM

14. I hereby certify that the foregoing is true and correct.

Signed

Title President

Date 3/4/97

(This space for Federal or State office use)

Approved by

/s/ Duane W. Spencer

Title

Date 9 1997

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

NMOC

Hanson 33  
Request to plug & abandon

1. TIH with 2 7/8" Tbg openended, Tag PBTD @ 1478'. Mix, pump & spot 24 sx Class B cmt. @ 1478', POH to 1300' Circulate hole clean, shut down overnite WOC
2. TIH with Tbg. Tag cmt top at 1333', mix and pump 9.0 PPG mud to fill csg., POH with tbg.
3. TIH with 5½" casing cutters, cut casing at 1000' from surface, POH with tbg., POH and lay down 5½" csg.
4. TIH with 2 7/8' tbg. to 600', mix and pump 25 sx class B neat (Plug @ 600' - 575') POH with tbg. Shut-down overnite, WOC
5. TIH with tbg., Tag cmt plug @ 575', mix and pump 9.0 PPG mud from 575' - 290', POH with tubing to 290', mix and pump 25 sx class B cmt neat (plug @ 290' - 265'), POH with tbg., shut down overnite, WOC
6. TIH with tbg, Tag cmt plug @ 265', mix and pump 9.0 PPG mud 265'-140', POH with tbg to 140', mix and pump 65 sx class B neat (plug @ 140' - surface) POH with tbg. Shut down overnite, WOC
7. Tag surface plug and top off csg if necessary. Install P&A marker with well ID, rehabilitation to surface location as per BLM requirements.