

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Dome
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County McKinley

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator W T R Oil Company
3. Address of Operator Drawer LL, Cortez, Colo 81321
4. Location of Well UNIT LETTER G, 2395 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 20N RANGE 11W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6272 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug as follows:

1. Shoot 4½" casing off @ 3000'.
2. Place cement plug from 3100' back to 2950' with 22 sks.
3. Place 2nd plug from 2450' back to 2350' with 22 sks.
4. Place 3rd plug from 100' to surface with 22sks.

Place Plug & Abandon marker, clean up location and level pits.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James P. Hooley
APPROVED BY Original Signed by FRANK T. CHAVEZ

TITLE Co-operator
TITLE SUPERVISOR DISTRICT # 3

DATE April 9, 1980
DATE APR 11 1980

CONDITIONS OF APPROVAL, IF ANY: