

## STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIG BRAZOS ROAD AZTEC, NEW MEXICO B7410 (505) 334-6178

January 18, 1980

Fairfax Exploration, Incorporated 301-B Graceland S. E. Albuquerque, New Maxico 87108

Re: Bullseye #1Y C-19-15N-9W

Gentlemen:

Our records indicate that the referenced well has been completed in the Dakota formation. We have not received reports of this completion, nor of the Sallup recompletion, approved on 9-17-79. These reports are delinquent. Please file these reports immediately to avoid shut-in orders and fines.

If you have any questions, please call this office.

Yours truly, Snale 5. Chury

Frank T. Chavez

FTC:dh

DISTRIBUTION		Form C-103
21311112311311	·	Supersedes Old C-102 and C-103
ANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
11-5		
.s.c.s.		5a. Indicate Type of Lease
AND OFFICE		State Fee Y
PEHATOA 3		5. State Oil 6 Gas Lease No.
CINODY NOTICE		mmmmmm.
(DO NOT USE THIS FORM FOR PHOPOSALS TO O USE "APPLICATION FOR PERA	ES AND REPORTS ON WELLS mill on to defer n on flug back to a different aebeavoi wit —" (romm (E-101)) for such proposals.)	• (1)
	·	7. Unit Agreement Name
OIL GAS WELL OTHER-		
		8. Farm or Lease Name
Fairfax Exploration, Inc. Address of Operator		Bullseve 9. Well No.
301-B Graceland S.E. A	lbuquerque, New Mexico 87108	' 1_Y
Location of Well		10. Field and Pool, or Wilacat
UNIT LETTER C 430	FEET FROM THE North LINE AND 1750	reet room Marcelina Dak
		THITTHINING
THE WEST LINE, SECTION 19	TOWNSHIP 16N MANGE GW	NMPM. []]]]]]]]
	15. Elevation (Show whether DF, RT, GR, etc.)	i2. County
	7200	McKinley
Check Appropria	te Box To Indicate Nature of Notice, Repo	<u> </u>
NOTICE OF INTENTION		SEQUENT REPORT OF:
HEORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
MPCHARILY ASAHDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
LL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JQ	• 🔲
other Complete as producing oi	OTHER	
-		·
Describe Proposed or Completed Operations (Ch. work) SEE RULE 1703, 4	early state all pertinent details, and give pertinent dates	, including estimated date of starting any proposed
OPERATOR	MAME CHANGE	State I American Brown to
1. Pull tubing.	Lease	1 4
2. Run cement bo		
	lug 150' below top of Gallup.	•
4. If necessary,	, perforate and squeeze cement belo	
5 WOC 48 has		ow Hospah sand (Upper Gallup).
5. WOC 48 hrs.	•	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos	spah (Upper Gallup).	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi	•	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well.	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well.	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat. rods.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat.	ow Hospah sand (Upper Gallup).
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat.  rods.	
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat. rods.	DATE Sept. 13, 1979
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat.  rods.  rods.  and complete to the best of my knowledge and belief.  ritte President	DATE Sept. 13, 1979
5. WOC 48 hrs. 6. Perforate Hos 7. Run tubing wi 8. Swab well. 9. Run pump and 10. Test well.	spah (Upper Gallup). ith pump seat.  rods.  rods.  and complete to the best of my knowledge and belief.  ritte President	