orm 3150-5  November 1983)  Formerly 9-331)  DEPARTMENT OF THE INTERIOR verse side)	Expires Augus  5. LEASE DESIGNATION	No. 1004-0135 t 31, 1985
BUREAU OF LAND MANAGEMENT	ľ	oint Venture
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IP INDIAN, ALLOTTE	S OR TREES NAME
	Jicarilla A	pache
OIL WELL OTHER	• • • • • • • • • • • • • • • • • • • •	
Meridian Oil Inc.	8. PARM OR LEASE NAI Jicarilla J	
ADDRESS OF OPERATOR	9. WELL NO.	-
P.O. Box 4289 Farmington, New Mexico 87499  LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	101	
See also space 17 below.)  At surface  890'S, 1020'E	10. PIRLD AND POOL, OR WILDCAT	
	S. Blanco PC 11. SEC., T., E., M., OR BLE, AND	
	Sec. 4, T23N, R3W	
PREMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)	NMPM 12. COUNTY OR PARISH	19
7297¹KB	Rio Arriba	NM
Check Appropriate Box To Indicate Nature of Notice, Report, or Ol		
	BNT BEFORT OF:	
FRACTURE TREAT  PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREATMENT  FRACTURE TREATMENT	REPAIRING V	
SHOOT OR ACIDIZE ABANDON" X SHOOTING OR ACIDIZING	ARANDONME	<del></del>
REPAIR WELL CHANGE PLANS (Other)		
(Other) (Nots: Report results of Completion or Recomplet	of multiple completion	on Wall
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug	including estimated data depths for all markers are excess plug and record tor	e of starting any and sones perti-
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
ment to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above 0jo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical ment to this work.)*  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
DOES (RIDE ENGROSSED ON CONPERTIONS (Clearly state all pertinent details, and give pertinent dates, in proposed work if well is directionally drilled, give subsurface locations and measured and true vertical ment to this work.)  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	ection Report and Log for including estimated data depths for all markers are excess plug and record top vics mud. Per	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	excess plug and record top vics mud. Pen surface and c	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.	excess plug fand record top vics mud. Pen surface and c	e of starting any and sones perti-
The proposed work if well is directionally drilled give subsurface locations and measured and true vertical ment to this work.)  This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.  SLE ATTACHED FOR CONDITIONS OF APPROVAL  I hereby certify that the foregoing is true and correct signed. TITLE Regulatory Affairs as (This space for Federal or State office use)	excess plug fand record top vics mud. Pen surface and c	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.  SLE ANACHID FOR CONDITIONS OF APPROVAL TITLE Regulatory Affairs (5) TITLE Regulatory Affairs (5) TITLE CONDITIONS OF APPROVAL IF ANY:	excess plug and record top vics mud. Pen surface and c	e of starting any and sones perti-
This well will be plugged and abandoned by:  MOL & RU. Kill PC as needed. Spot 67 sx (79cf) cement for a 50% 3264'-2681' (perfs to 50' above Ojo Alamo). WOC 6 hrs. tag plug (TOC outside csg 2304' calc. 75% eff). Circulate 43 bbls 9.2# 50 holes @ 194'. Circulate 80 sx (94.4 cf) cement (100% excess) from bradenhead.  Cut off wellhead and set dry hole marker with 10 sx cement.  Cut off wellhead and set dry hole marker with 10 sx cement.  Cut off certify that the foregoing is true and correct signed.  I hereby certify that the foregoing is true and correct signed.  Cities space for Federal or State office use)	excess plug and record top vics mud. Pen surface and c	e of starting any and sones perti-

## BUREAU OF LAND MANAGEMENT 1235 La Plata Highway Farmington, New Mexico 87401 Phone (505) 327-5344

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 101 Jicarilla Joins Venture PC

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 327-5344.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.

## GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6%/gal slurry weight is to be used when using class B neat cement or when CaCl<sub>2</sub> is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
  - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

  Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.