

J

30-039-23742

6-13-85

F. Loc. 655/S; 960/E Elev. 6745 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS		NiTD ☒	Well Log	TEST DATA						
Ojo Alamo		C-103	Plot ☒	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menelee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres 40								

P
o
o
i

WC Gal. Co. RA S 6 T23N R 5W U P Oper. W.B. Martin & Assoc. Lse. Martin-Whittaker No. 77

J

30-039-23742

6-13-85

F. Loc. 655/S; 960/E Elev. 6745 GL Spd. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. Gas
 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres 40								

P
o
o

I WC Dak. Co. RA S 6 T 23N R 5W U P Oper. W.B. Martin & Assoc. Lse. Martin-Whittaker No. 77

Martin-Whittaker #77

P-6-23N-5W

W.B. MARTIN & ASSOCIATES

Caller Service 4104
Farmington, New Mexico 87499

JUN 25 1986

CERTIFYING--RETURN RECEIPT REQUESTED

W. B. Martin and Associates
709 N. Butler
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) wells No. 77 Martin-Whittaker, SESE sec. 6, T. 23 N., E. 5 W. and No. 78 Martin-Whittaker, SEMW sec. 6, T. 23 N., E. 5 W., both in Rio Arriba County, New Mexico, lease Jicarilla 38. The subject APDs are being returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,


FOR John S. McKee
Acting Area Manager

Enclosure

cc:
MFOCD

RECEIVED
JUN 27 1986
OK
1986

ABANDONED LOCATION