Form approved. Budget Bureau No. 42-R1424. Form 9-331 (May 1963) UNITED STATES SUBMIT IN TRIPLICATE*
DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) UNITED STATES 5. LEASE DESIGNATION AND SERIAL NO. SF 078656-I GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL GAS WELL 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Arwood H. Stowe Retir 3. ADDRESS OF OPERATOR 9. WELL NO. P. O. Rox 2265. Michita Falls, Toxas 1-1 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELE AND POOL, OR WILDCAT San Inis 1980' from North Line 11. SEC., T., R., M., OR BLW. AND SURVEY OR AREA 509' from East Line Section 21, TIEM, ESW Sec. 21, 181, 31 12. COUNTY OR PARISH | 13. STATE 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) New Yorkeo Sandeval. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: REPAIRING WELL TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF ALTERING CASING MULTIPLE COMPLETE FRACTURE TREAT FRACTURE TREATMENT ABANDON* SHOOTING OR ACIDIZING ARANDONMENT* SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* We re-entered the 1-H Kathy well and cleaned it out. We re-worked the pump and bailed hole. Well is now on the puny and is pumping 60% oil and 40% water at this time. The water appears to have built up over a period and will have to be pumped down. We were unable to dislodge object in hole. If we continue to have trouble, we will have to run an impression block to hay and deferring what is in the pipe. It is. possible that we could have part all applied pipe.



AUG 114 1967

U. S. GEOLOGICAL SURVEY FARMING COM, N. 100

18. I hereby certify that the foregoing is true and correct		
SIGNED House	TITLE CONTROLOR	DATE
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE