### 8. Ancillary Facilities

No camps or airstrips will be used.

### 9. Wellsite Layout

See attached topographic map.

# 10. Plans for Restoration of Surface

Will be restored in accordance with current Bureau of Land Management specifications as indicated in attached memorandum with surface owner Mr. Eugene Johnson, Cuba, N.M.

#### 11. Other Information

The topography of the area in the vicinity of the well and roads is a gently sloping sandy soil covered with sage brush and sparse vegetation.

## 12. Operators Representative

Minerals Management, Inc. 501 Airport Dr., Suite 105, Farmington, New Mexico 87401.

## 13. Certification

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Filon Exploration Corporation and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved.

6-11-76 Date

Name and Title

Minerals Management, Inc.

Company