

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 26164

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bicentennial Freedom

9. WELL NO.

Federal No. 1

10. FIELD AND POOL, OR WILDCAT

wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

sec 35, T13N, R6E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6260 GR

12. COUNTY OR PARISH

Sandoval

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) 2 open hole tests

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9/22/76 - Rigged up over hole. 9/23/76 - cleaned out 6 1/2" hole to 734'. 9/26/76 finished leaning out and conditioning hole to 1415 feet. 9/27/76 ran in hole with Lynes Enflat-able Packer on 2-3/8" EUE tubing and set 1220-24. Swabbed down to packer. Swabbed intermittently for 24 hrs. Recovered mud and watery mud with no shows of oil or gas. 9/28/76 attempted to set packer at 1098-1102. Could not get seat. Came out of hole redressed packer and set 993'-97'. Swabbed down to packer. Swabbed intermittently for 20 hrs. Very little fluid entry. Swabbed mud with no oil or gas shows. In accordance with oral instructions from Mr. Jerry Long, District Engineer, USGS, spotted cement plugs as follows: 1080-980 - 20 sx  
410-270 - 28 sx  
surface casing - 10 sx

Will notify USGS when dry-hole marker set and location cleaned up.

18. I hereby certify that the foregoing is true and correct

SIGNED

Mark E. Weidler

TITLE Vice President

DATE 10/6/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE