Form: 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES EPARTMENT OF THE INTER BUREAU OF LAND MANAGEMEN	/	Form approved. Budget Bureau N Expires August 5. LEASE DESIGNATION NM-29168	31, 1985 AND SERIAL NO.
SUNDRY (Do not use this form Use	NOTICES AND REPORTS for proposals to drill or to deepen or plug "APPLICATION FOR PERMIT—" for such 1	ON WELLS back to a different reservoir. proposals.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
OIL X GAS WELL X	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR	8. FARM OR LEASE NAME			
Gary-Williams Oi	Tayler 29			
3. ADDRESS OF OPERATOR			9. WELL NO.	
P. O. Box 399 Az	#9			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface			Undesignated-Gallup	
677' FEL & 2	11. SEC., T., B., M., OR BLK. AND. SURVEY OR ARMA			
RECEIV	Section 29,			
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OF PARISH	18. STATE
NOV 07 1985	· · · · · · · · · · · · · · · · · · ·	6954	Sandoval	NM
	heck Appropriate Box To Indicate I	Nature of Notice, Report, or C	Other Data	
BUREAU OF LAND MANAGE FARMINGTON RESOURCE	MENT OF INTENTION TO:	EUBBEUE	UENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	PELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	BING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDISING	ABANDONMEN	J T ♦

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) •

CHANGE PLANS

(Other) Recomplete in Menefee Coal seam

11-7-85 GWOP respectfully requests permission to recomplete the referenced well in the Menefee coal seams as follows. Note: Potential productive intervals will be behind 23#, 7" Intermediate casing which was cemented to surface.

1. Move in and rig up completion unit. Pull out of hole with rods & tubing.

(Note: Report results of multiple completion on Wall Completion or Recompletion Report and Log form.)

2. Set cast-iron plug @ 4730' and spot 50 sx cement on top of plug.

3. Perforate select coal seams in the interval 3050'-3550' KB.

- 4. Test individual coal seams via straddle packer for productivity. Break down if necessary with 2% KCl water.
- 5. If additional stimulation is required, frac with foamed KCl water containing 50,000# to 60,000# of 8/10 sand.
- Flow/swab to evaluate and determine production method and/or water disposal (if necessary).
- 7. Production from the Gallup interval of this well has been non-commercial.
- 8. After frac load is recovered, the produced water volumes (if any) and quality will determine the method of disposal and the appropriate permits will be filed.

		A STATE OF THE PERSON OF THE P
	·	
18. I hereby certify that the foregoing is true and correct SIGNED Lead Nation	Agent	November 7, 1985
(This space for Federal or State office use)		NOV 0 7 1005
CONDITIONS OF APPROVAL, IF ANY:	NOV 12 1985	Jan Skill
eh?	CHAMA DIV.) See Instructions Of Reverse Side	Full State Control of the Control of
	*****	Contraction and the second of