

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved/
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.
terminated lease
SF 079021
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐
2. NAME OF OPERATOR
Noel Reynolds
3. ADDRESS OF OPERATOR
Box 356 Flora Vista, New Mexico 87415
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
790' FR NL, 1850' FR EL SEC 14 T22N R6W
Sandoval Co., New Mexico
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
7083 GL

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
N. Reynolds
9. WELL NO.
1 Silvers
10. FIELD AND POOL, OR WILDCAT
wildcat
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
14-T22N R6W
12. COUNTY OR PARISH
Sandoval
13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Final Abandonment;

1. Spot cement plug over perfs. 5250 to 5475 w/23 sacks cement
2. Plug at 3250 to 3350 inside 5½ casing 10 sx.
3. Shot casing at 2223' spotted 50' outside and 50' inside stub W/10 sx. cement.
4. Plug 1300 to 1900 W/31 sx.
5. Plug 1275 to 1475 W/62 sx.
6. Plug 375 to 475 50' in and out of surface
7. Set 15 sx. with marker at surface.
8. Leveled pit and cleaned location.

18. I hereby certify that the foregoing is true and correct

SIGNED *Noel Reynolds*

TITLE operator

DATE 2/27/75

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side