## UNITED STATES

_		JAIN.			LOTT	 O TOU	· · ·
	TAT	-1-TO	OU.	フ			
	RÌR	4-13	600	0			

5. LEASE

DEPARTMENT OF THE INTERIOR	NM-13609
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)  1. oil  gas well  well  other	8. FARM OR LEASE NAME Midway 9. WELL NO.
2. NAME OF OPERATOR Tenneco Oil Company	2 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155	Undes. 11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 717' FSL, 2214' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 22, T22N, R8W  12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD
REQUEST FOR APPROVAL TO:  SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  SUBSEQUENT REPORT OF:  SUBSEQUENT REPORT OF:  TO SUBSE	NOTE Report results of multiple completion or zon change on Form 9–330.)
ABANDON* U. s. Garage	Endayer Transfer

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

In accordance with the request by the U.S.G.S., Tenneco proposes to plug and abandon the above referenced well as detailed in the procedure attached.

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct 1/22/82 TITLE Production Analyst DATE \_ for Federal or State office use) APPROVED BY \_ CONDITIONS OF \_ DATE \_ for JAMES F. SIMS DISTRICT ENGINEER

**NMOCC** 

#ELL NO			1			•	TEV2E	Midway	
Probable open hole  DETAILED PROCEDURE  1. Set anchors on location.  2. MIRUSU.  3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  K See affected wodifications.  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole						WEL	L 1:0.	2	
Probable open hole  DETAILED PROCEDURE  1. Set anchors on location.  2. MIRUSU.  3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  ** See affected modifications.  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole									SX
Probable open hole  DETAILED PROCEDURE  1. Set anchors on location.  2. MIRUSU.  3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  **See affected wodifications**  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole	4-1/2				•	·			
DETAILED PROCEDURE  1. Set anchors on location.  2. MIRUSU.  3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  **See attacked modifications.  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole					OD,	LE,	csg.W	/	Sx
1. Set anchors on location. 2. MIRUSU. 3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish). 4. Fill hole from btm to surface w/class 'B' neat cmt.  ** See allacked modifications. 5. RDMOSU. 6. Cut off 4-1/2" csg & install P&A marker. 7. Clean, grade & re-seed location.  Drill pipe & collars in hole				TOC @ _			<b>-•</b>	•	
2. MIRUSU.  3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  * See allocked modifications.  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole	Probable open hole	·		DETAILE	D PROCEDURE				
3. RIH w/2-3/8" tbg & bit & CO to PBTD (top of fish).  4. Fill hole from btm to surface w/class 'B' neat cmt.  **See attached modifications.*  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole	×	-		1. Set	t anchors on	location.			
4. Fill hole from btm to surface w/class 'B' neat cmt.  **See allached modifications.  5. RDMOSU.  6. Cut off 4-1/2" csg & install P&A marker.  7. Clean, grade & re-seed location.  Drill pipe & collars in hole				2. MI	RUSU.				
5. RDMOSU. 6. Cut off 4-1/2" csg & install P&A marker. 7. Clean, grade & re-seed location.  Drill pipe & collars in hole									•
7. Clean, grade & re-seed location.  Drill pipe & collars in hole				4. Fi ** 5 5. RDI	ll hole from See attack MOSU.	btm to surfa ed moditi	ce w/class cations.	'B <b>' ne</b> at (	emt.
Drill pipe & collars in hole				6. Cu	t off 4-1/2"	csg & instal	1 P&A marke	r.	
				7. Cl	ean, grade &	re-seed loca	tion.		
?			Drill p & colla	ipe rs in hol	e				
?			·		•	•			
?								•	<u>,</u>
?									· · · · · · · · · · · · · · · · · · ·
?									e e e e e e e e e e e e e e e e e e e
?	٠								
?	•								
?									
?									
	?	4							

## U. S. GEOLOGICAL SURVEY Drawer 600 Farmington, New Mexico 87439-00800

Attachment to Notice of Intention to Abandon

Re: Permanent Abandonment

Hell: 2 Midway

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the actached [General Requirements for Permanent Abandonment of Walls on Federal Leases."

- The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Clowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. highing of pad and/or access road, reseading, etc. We have asked the Duneau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final close to the context this office unless you had before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. The following modifications to your plugging program are to be made (when applicable):

Locate free point of 42 casing. If free point is at surface, proposed PAA program is satisfactory.

- If free point is below 1300 or 350 or surface,

  a) perforate 4½" casing at 1400' and spot cement plug
  inside and outside casing from 1400' to 1300' to
  cover chacra top.
  - b) perforate 4/2 casing at 450' and spot cement plug inside and antside casing from 450' to 350' to cover
  - Fruitland top.

    c) perforate 4½" casing at 80' and spot cement plug inside and artside casing from 80' to surface to cover 0jo Alamo top.

Office Hours: 7:30 A.M. to 4:15 P.M.