Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

rorm C-1W
Revised 1-1-89

DISTRICT I	OIL CONSERVATION	NA DI A 1210M	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 20		30-039-05238
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III			6. State Oil & Gas Lease No.
000 Rio Brazos Rd., Azzec, NM 87410			E-1207
	CES AND REPORTS ON WE		
DO NOT USE THIS FORM FOR PRODIEFERENT RESER	PPOSALS TO DRILL OR TO DEEPEN IVOIR. USE "APPLICATION FOR PE	I OR PLUG BACK TO A RMIT	7. Lease Name or Unit Agreement Name
(FORM C-	101) FOR SUCH PROPOSALS.)		NCRA State
Type of Well: OIL GAS WELL X			
WELL X Name of Operator	OTHER		
Benson-Montin-Greer Dr	illing Corp.		8. Well No.
. Address of Operator			9. Pool name or Wildcat
4900 College Boulevard	, Farmington, NM 874	02	Ballard Pictured Cliffs
. Well Locauon	16		200
Unit Letter 1 : 10	10 Feet From The SOULI	Line and9	990 Feet From The <u>east</u> Line
Section 36		tange 6W	NMPM Rio Arriba County
	10. Elevation (Show whether		
(/////////////////////////////////////		Name of Nation	Parama Orban Param
	Appropriate Box to Indicate		•
NOTICE OF INT	TENTION TO:	50	BSEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON XX	REMEDIAL WORK	ALTERNIC CASING
	LOG KIND KOMINDON WAN	HEMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLII	
TEMPORARILY ABANDON	_		NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	_	COMMENCE DRILLII CASING TEST AND	NG OPNS. PLUG AND ABANDONMENT
ULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLII CASING TEST AND	NG OPNS. PLUG AND ABANDONMENT
OTHER:	CHANGE PLANS	COMMENCE DRILLII CASING TEST AND	NG OPNS. PLUG AND ABANDONMENT
OTHER: 12. Describe Proposed or Completed Operawork) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLII CASING TEST AND OTHER: and give persinent dates, inc	PLUG AND ABANDONMENT CEMENT JOB cluding estimated date of starting any proposed NOTIFY AZTEC OCD
THER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296. Propose to plug by fi	CHANGE PLANS DELIONS (Clearly state all pertinent details. TD 2311'. Open hole lling entire hole wit	COMMENCE DRILLII CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD
ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'.	CHANGE PLANS DELIONS (Clearly state all pertinent details. TD 2311'. Open hole lling entire hole wit	COMMENCE DRILLII CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS
ULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operation of the Proposed of Completed Operation (Casing set at 2296'). Propose to plug by finand squeezing with a management of the Propose of the Prop	TD 2311'. Open hole cling entire hole witminimum of 200 psi.	COMMENCE DRILLII CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS a minimum of 300 sacks
ULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a reward of the squeezing with a	TD 2311'. Open hole alling entire hole with minimum of 200 psi.	COMMENCE DRILLING CASING TEST AND OTHER: and give periment dates, income 2296' to the cement, using	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS 3 a minimum of 300 sacks
ULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a rule will plug before Nove	TD 2311'. Open hole cling entire hole witminimum of 200 psi.	COMMENCE DRILLII CASING TEST AND O OTHER: and give periment dates, ince from 2296' to h cement, using	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS OCT 1 3 1998
ULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many squeezing with a many squeezing with a many squeezing before Nove for the first square of the first square	TD 2311'. Open hole alling entire hole with minimum of 200 psi.	COMMENCE DRILLING CASING TEST AND OTHER: and give persinent dates, income 2296' to the cement, using	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed 2311'. NOTIFY AZTEC OCD IN TIME TO WITNESS OCI 1 3 1998 OCI 1 3 1998
ULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many squeezing with squeezing with a many squeezing with a many squeezing with a many squeezing with squeezing w	TD 2311'. Open hole ling entire hole wit minimum of 200 psi.	commence Drilling CASING TEST AND COTHER: and give persinent dates, income 2296' to the cement, using Casing Casi	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS OCT 1 3 1998
ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many squeezing with squeezing with a many s	TD 2311'. Open hole ling entire hole wit minimum of 200 psi.	commence Drilling CASING TEST AND COTHER: and give pertinent dates, income 2296' to the cement, using the comment of the comm	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed 2311'. NOTIFY AZTEC OCD IN TIME TO WITNESS OCI 1 3 1998 OCI 1 3 1998
OTHER: 12 Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many squeezing with squeezing with a many squeezing with	TD 2311'. Open hole ling entire hole wit minimum of 200 psi.	COMMENCE DRILLING CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to h cement, using And Cartage	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed 2311'. NOTIFY AZTEC OCD IN TIME TO WITNESS OCI 1 3 1998 OCI 1 3 1998
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many with a many squeezing with a many sq	TD 2311'. Open hole ling entire hole wit minimum of 200 psi.	COMMENCE DRILLING CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to h cement, using And Cartage	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS. G a minimum of 300 sacks OCI 1 3 1998 OCI 2 3 1998
DTHER: 12. Describe Proposed or Completed Operawork) SEE RULE 1103. Casing set at 2296'. Propose to plug by fi and squeezing with a many with a man	TD 2311'. Open hole ling entire hole wit minimum of 200 psi.	COMMENCE DRILLING CASING TEST AND O OTHER: and give persinent dates, inc from 2296' to h cement, using And Cartage	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed NOTIFY AZTEC OCD IN TIME TO WITNESS OCI 1 3 1998 OCI 1 3 1998 OCI 3 1998

661 1 3 1334

The second secon