

F. Loc. 915/N; 1035/W Elev. 576 GL Spd. 1/7/55 Comp. 1/28/55 TD 2340 PB 2316
 Casing S. 8 1/2 @ 97 W 90 Sx. Int. @ W Sx. Pr. 56 @ 2314 W 100 Sx. T. 2 @ 2305
 Csg. Perf. 76 shots 2164-2202 Prod. Stim. 70 shots 2220-2240
 I.P. 5906 ~~BO/D~~ MCF/D After 3 Hrs. SICP 708 PSI After 7 Days GOR Grav. 1st Del. 3-14-56 5-10-56

TOPS		NITD	Well Log	TEST DATA						
Kirtland		C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103	Electric Log							
Pictured Cliffs	<u>2164</u>	C-104	C-110 <u>5/15/56</u>							
Cliff House		<u>5-15-56</u>	C-122-E							
Menefee		Ditr	Dfa							
Point Lookout		Datr	Dac							
Mancos		Remarks								
Tocito										
Dakota										
Morrison										
Entrada										

P
O
Otero FC Co. RA S 33 T 24N R 5W U C Oper. Mike Abraham Lse. Cicarilla No. 11
 Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec.