

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. <i>Jicarillo Contract #12</i>
2. NAME OF OPERATOR <i>Mobil Oil Corporation</i>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME <i>Jicarillo Apache</i>
3. ADDRESS OF OPERATOR <i>P.O. Drawer G, Cortez, Co. 81321</i>	7. UNIT AGREEMENT NAME <i>-</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1650' FNL, 1650' FEL</i>	8. FARM OR LEASE NAME <i>Jicarillo Otero</i>
	9. WELL NO. <i>2</i>
	10. FIELD AND POOL, OR WILDCAT <i>Otero - Gallup</i>
	11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA <i>Sec 28, T24N, R5W</i>
14. PERMIT NO.	12. COUNTY OR PARISH <i>Rio Arriba</i>
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <i>6607' GL</i>	13. STATE <i>N.M.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST (WATER SHUT-OFF)	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACURE TREAT	MULTIPLE COMPLETE	FRACURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED, OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On July 6, 1987 the subject well was entered to locate a suspected casing leak. Subsequent testing indicated a hole in the casing between 627' and 649'. Since this is located in an interval of fresh water, repair is proposed as follows:

1. Set pkv above hole. W/ braedenhead open, pump neat Class B cement until cement returns are obtained (est 155 cuft.)
2. Shut in braedenhead and pump additional cement until squeeze obtained.
3. DO cement, test leak and return well to production.

The above procedure was verbally approved by Steve Wlasen on 7.9.87

18. I hereby certify that the foregoing is true and correct	TITLE <i>Sr Staff Op Engr</i> DATE <i>7.10.87</i>	
SIGNED <i>[Signature]</i>		
(This space for Federal or State office use)		
APPROVED BY <i>[Signature]</i>	TITLE <i>[Signature]</i> DATE <i>[Signature]</i>	
CONDITIONS OF APPROVAL	APPROVED	

See Instructions on Reverse Side