	UNITED STATES SUBMIT IN TRIPLICATES SUBMIT IN TRIPLICATE (Other Instructions on re		5. LEASE DESIGNATION AND SEELAL NO. SF-078562	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTER OR TRIBE NAME	
I.  OIL CAR OTHER  WELL OTHER			7. UPIT AGREEMENT NA	
2. NAME OF OPERATOR			Largo Spur	
Flag-Redfern Oil Company  3. ADDRESS OF OFERATOR P.O. Box 208, Farmington, NM 87499			9. WHILL BO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any		tate requirements.	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface  2160 FSL - 1770 FEL			Devils Fork - Callup  11. BNC, T, E, M, OR BLE, AND SORVEY OR ABBA  Sec. 18, T 24N, R 6W, NMPM	
		•		
14. PERMIT NO.	15. BLEVATIONS (Show whether DF. 65491 GL; 65601 RF		Rio Arriba	NM NM
16. Check A	ppropriate Box To Indicate No		ther Data	
NOTICE OF INTENTION TO:			GENT EBPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIES REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	Completion or Recomple	ALTERING CA ABANDONMEN  of multiple completion completion Report and Log for	na Well
Plan to plug & aban	don this well as follows:	as and measured and true vertical	deptas tor an markets	and somes perti-
cement into pe	rfs and 15 sx inside cas	ing from 5470' - 5340'.		
(2) Spot 100' ceme	nt plug from 3600' - 350			
(3) Spot 100' ceme	ikc <del>195</del> - ht plug from 2050			
(4) Spot 100° ceme	nt plug from 100¹ - 0¹.		EGEIVE	Ď
(5) Install dry hole	e marker.		AUG 2 1 1987	
(6) Clean and rest	ore location.	Oll	CON DIV.	3
S. I hereby certify that the foregoing is SIGNED Jim L. Jacobs (This space for Federal or State office)	TITLE A	gent	DATE 8-1	7-87
APPROVED BY CONDITIONS OF APPROVAL, IF A	TITLE		TO ADEA NA	1987 VÅGER

## BUREAU OF LAND MANAGEMENT CALLER SERVICE 4104

FARMINGTON, NEW MEXICO 87499

Attachement of Notice of

Re: Permanent Abandonment

Intention to Abandon

## CONDITIONS OF APPROVAL

- Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
- Blowout prevention equipment is required.
- The following modifications to your plugging program are to be made (when applicable): Add this plugs to program.
  - a) Spot a plug from 4972 4872' Gallup
  - b) fert @ 3625' and pluy to inside Lourside 51/2" Casing from 3625'-3525' Messerele
  - c) feet @ 2447 and plug inside doutside 5/2" casing from 2447-2347 Check
  - d) Pluy from 2050' 1800' Proce-ed Clifts & Fruithand
  - e) plug from 1573'-1353' Ojo Alamo
  - f) plug from 292'-192' Surface Casing Shoe
  - e) Braiden head Squeez with enough coment to cover from Surface to 292'

Office Hours: 7:45 A.M. to 4:30 P.M.

## GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 25 sacks or 100 feet in length, whichever is greater.
- 5. Any cement plug placed when well is not full of fluid, or when well may be taking fluid, will be touched after cement has set to verify proper location.
- 6. Mud must be placed between plugs. Minimum consistency of plugging mud must be 9.2 lbs/gal. Brine is to be utilized for mixing mud where possible.
- 7. Within 15 days after plugging work is completed, file Subsequent Report of Abandonment, Form 3160-5, in quintuplicate with Area Manager, BLM, Caller Service 4104, Farmington, New Mexico 87499. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. All permanently abandoned wells are to be marked with a regulation marker.
- 9. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to technical and procedural review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.