

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY •

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	6. IF INDIAN, ALLOTTEE OR TRIBE NAME JICARILLA CONT #127
2. NAME OF OPERATOR NORTHWEST PRODUCTION CORP.	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR P.O. BOX 1796, EL PASO, TEXAS 79949	8. FARM OR LEASE NAME S
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1600' FSL, 1080' FEL, Sec 10-T24N-R4W, Unit I	9. WELL NO. 9
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT SOUTH BLANCO P.C.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6757 GR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 10, T24N, R4W
	12. COUNTY OR PARISH Rio Arriba
	13. STATE New Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input checked="" type="checkbox"/>
(Other) Attempt completion in new zone.			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 2982' PBTD 2980' Propose to plug P.C. from 2912' to 2550'. Pressure test csg and spot acid over Kirtland formation and perf w/5 shots from 2515' to 2530'. Breakdown formation and swab test zone. Estimated date May 15, 1969.

If unsuccessful will squeeze Kirtland perforations with sufficient cement to cover Ojo Alamo formation and leave 200' plug in casing. Will squeeze bradenhead with 50 sacks and place 10 sack plug in top of casing and place dry hole marker on well.



18. I hereby certify that the foregoing is true and correct

SIGNED Charles E. Warner TITLE Mgr., Prod. Oper.

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____



*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.