

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-R142

5. LEASE DESIGNATION AND SERIAL NO.

SF-078959

6. IF INDIAN, ALLOTTEE OR TRIBAL NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 1-7

9. WELL NO.

1

10. FIELD AND FORM. OR WILDCAT

Dufers Point Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

7-24N, 7W N.M.P.M.

12. COUNTY OR PARISH

Rio Arriba

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

990' FSL 990' FEL Section 7 T24N R7W N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

7344 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of start of proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

Intend to plug and abandon well, Will do the following:

Set 25 sack plug across Gallup perforation 6218-6228.

Perforate at 3450, set 300' plug from 3300-3600, squeeze at 3450.

Perforate at 2150, set 300' plug from 1900-2200, squeeze at 2150.

Fill 4 1/2 from 310 to surface.

Pump 40 sacks down bradenhead.

Weld dry hole marker to 4 1/2.

Verbal approval of above work obtained by Don Patton from U.S.G.S on 7-15-80

18. I hereby certify that the foregoing is true and correct

SIGNED *Harry R. Blum*

APPROVED

TITLE President

DATE 8/18/80

(This space for Federal or State (if any) 1980

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

DISTRICT ENGINEER

TITLE

NMOC

DATE