(SUBMIT IN TRIPLICATE)

*

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Allottee Jiegrille Pribel
Lease No. .. Contract 111

	TO DOUL	SUBSEQUENT REPORT OF WATER	SHUT-OFF	
NOTICE OF INTENTION NOTICE OF INTENTION	TO DRILL	SUBSEQUENT REPORT OF SHOOT		
= =	TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	
	TO REDRILL OR REPAIR WE		·	
	TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABAND		
	TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION				
TOTION OF INTENTION			RECEIVE	
ell No		THECK MARK NATURE OF REPORT, NOTICE, OR OTHER ADDITIONS Of the from $\{N\}$ line and 1600 ft. f	FARMINGTON, NEW MEANS	
/h_104/h_1h	<u> </u>	(Bange) (Seriosa)	P.A. MITTO	
(% Sec. and Sec	(TWP	Rig Arriba	- LOLLIVIN	
(Field)		(County or Subdivision)	(State or Teritory)	
•		·	APR 95 1057	
he elevation of	the derrick floor abo	ove sea level is _6785 ft.	A 1 20 (55)	
			OR CON. COM	
		DETAILS OF WORK	DIST. 3	
ate names of and ex	pected depths to objective sar ing poi	nds; show sizes, weights, and lengths of proposed coints, and all other important proposed work)	asings; indicate in adding jobs, coment-	
i- 3-57 !- !- 9-57	J-99 casing at	Set 87 joints 29601 of t 2972' with 100 sacks of wavey showed top of come on casing to 1000%. Ho		
t- 3-57 t- 9-57	J-99 casing at	mand sponey tob of come		
t- 3-57 t- 9-57	J-99 casing at Temperature of Pressured up (mand sponey tob of come		
i- 3-57 i- 9-57	J-99 casing at Temperature of Pressured up (mand sponey tob of come		
i- 3-57 I- 9-57	J-99 casing at Temperature of Pressured up (mand sponey tob of come		
i- 3-57 I- 9-57	J-99 casing at Temperature su Pressured up o is one hour.	ervey showed top of same on easing to 1000. He	nt at 2325'. proceure decrease	
i- 3-57 i- 9-57	J-99 casing at Temperature su Pressured up o is one hour.	mand sponey tob of come	nt at 2325'. proceure decrease	
4- 3-57 4- 9-57	J-99 casing at Temperature su Pressured up o is one hour.	ervey showed top of same on easing to 1000. He	nt at 2325'. proceure decrease	
I understand that	J-99 casing at Temperature su Pressured up o is one hour.	ervey showed top of same on easing to 1000. He	nt at 2325'. proceure decrease	
I understand that to	J-99 casing at Temperature su Pressured up o is one hour.	ervey showed top of same on easing to 1000. He	nt at 2325'. proceure decrease	
- 3-57 - 9-57 I understand that to ompany #1. P	J-99 casing at Temperature su Pressured up o is one hour.	ervey showed top of same on easing to 1000. He	nt at 2325'. proceure decrease	

U. S. GOVERNMENT PRINTING OFFICE 16-8487b-

