

Multi-Point Surface Use and Operations Plan

1. Existing roads: Attached map shows existing road running from the West edge of Section 34 Eastward to the Section line, then Northwest past the proposed location.
2. Planned Access road: None.
3. Location of Existing wells: W M Gallaway #1 Myers, Section 35, Township 25 North, Range 3 West, Rio Arriba County, New Mexico.
4. Location of existing and/or proposed facilities: None.
5. Location and type of water supply: Water will be taken from a water hole 6 miles away and transported by truck to location.
6. Source of construction materials: None.
7. Methods for handling waste disposal: Cuttings to be disposed of in a reserve pit; a burn pit to be used for disposal of trash, garbage, etc.; and covered on clean-up of location.
8. Ancillary facilities: None.
9. Well site layout: Per attached drawing.
10. Restoration of Surface: Upon completion of drilling operations, the disturbed surface area will be restored as near as practical to its original contours. If sufficient top soil is encountered, it will be stockpiled for restoration of surface. Restoration will be to the satisfaction of the United States Geological Survey.
11. This location slopes approximately 8' per 100' to the Southeast. There will be approximately a 10 foot cut on the Northwest side of the proposed location. Vegetation is sage brush, pinon and juniper trees, scrub oak, snakeweed and grasses. The surrounding area is comparable and any disturbances to the wildlife will be only temporary. With the restoration of surface, surface damage will be minimal.
12. Lessee's or Operator's Representative: John E. Schalk, P. O. Box 25825, Albuquerque, New Mexico, 87125; or J.D. Christesson, 2301 Southside River Road, Farmington, New Mexico, 87401.