

F

30-039-21956

10-2C-78

F. Loc. 790/N; 790/E Elev. 7213 GL Spd. 10-24-79 Comp. 12-2-79 TD 610+ PB 4762Casing S. 85/8 @ 327 W 200 Sx. Int. @ W Sx. Pr. 4 1/2 @ 6100 W 565 Sx. T. @
Csg. Perf. Prod. Stim.T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. Ist Del. s

TOPS		NITD	Well Log	TEST DATA								
Kirtland	3350	C-103	✓✓✓✓✓	Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland	3497	C-104		Electric Log	✓✓							
Pictured Cliffs	3604		2°	C-122								
Chama Cliff House MV	4475 5220	Ditr		Dfa								
Menefee		Datr		Dac								
Point Lookout		+ Aunt 4-25-80 NIT P+ A MV 4-25-80										
Moncas												
Gallup												
Sanostee												
Greenhorn												
Dakota												
Morrison												
Entrada												

P
o
o

BA - 26 - 25N - 3W - A - 10-24-79 - 12-2-79 - 610+ - 4762

NI P+ A MV 4-25-80