Form 3160-5 (December 1989)

14. I hereby certify that the foregoing is true and correct

(This space for Federal or State office use)

Approved by /s/ David R. Sitzler

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

07/10/00

Date AUG 1 8 2000

Date

Expires:	September 30,	1990

BURRAU OF LA	AND MANAGEMENT	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals		5. Lease Designation and Serial No.
		Oir. 6. If Indian, Allottee or Tribe Name
00 JUL 12 PM 12: 57 SUBMIT I	N TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of WEN QUERQUE. N.M. OIL GAS WELL OTH 2. Name of Operator	ER	8. Well Name and No. Jicarilla Apache 148 #18
Amoco Production Company	Melissa Velasco-Price	9. API Well No. 30-039-22000
3. Address and Telephone No. P.O. Box 3092 Houston, TX 77253	(281) 366-2548	10. Field and Pool, or Exploratory Area Basin Dakota
4. Location of Well (Footage, Sec., T., R., M., or Survey $1850/N$ $1590/\omega$	Description) F-23-25N-5W	11. County or Parish, State Rio Arriba New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE O	F ACTION
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion	New Construction
	Plugging Back	☐ Non-Routine Fracturing ☐ Water Shut-Off
Final Abandonment Notice	☐ Casing Repair ☐ Altering Casing ☐ Other	Conversion to Injection
	(Note: Report results of Recompletion Report a	multiple completion on Well Completion or and Log form.)
13. Describe Proposed or Completed Operations. (Clework. If well is directionally drilled, give subsurfa	arly state all pertinent details, and give pertinent dates ce locations and measured and true vertical depths fo	, including estimated date of starting any proposed r all markers and zones pertinent to this work.)*
Amoco Production Company request procedure.	permission to Plug & Abandon the sub	ject well per the attached well work
		AUG 2000

Conditions of approval, if any:

Lands and Mineral Resources

Title Permitting Assistant

Title

Jicarilla Contract 148 18 (Lindreth Gallup Dakota)
Original Completion 5/79 Recompletion 5/80
TD = 7,700' PBTD = 7,300'
Page 2 of 2

Objective: PXA entire wellbore

- 1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 2 3/8" tubing. TIH with 2 3/8" tubing workstring and CIBP. Set CIBP at 6,346'. Spot cement plugs across each of the following:

<u>Formation</u>	<u>Formation Top</u>	<u>Cement Plug</u>
Lindreth Gallup Dakota	6,241′	6,346' to 6,191'
Cliff House	4,656′	4,706' to 4,606'

5. TOH with tubing workstring. TIH with CIBP and set at 3,835'. Spot cement plugs across each of the following:


<u>Formation</u>	Formation Top	Cement Plug
Chacra	3,883'	3,835' to 3,735'
Pictured Cliffs, Fruitland	2,890' (FT)	3,078' to 2,840'
Ojo Alamo	2,401′	2,451' to 2,351'

- 6. TOH, rig up wireline, TIH and perforate at 372'. Pump cement down casing and circulate cement to surface leaving casing full of cement.
- 7. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 8. Contact FMC and ship surface equipment to yard or other location per instructions.
- 9. Provide workorder to Buddy Shaw for reclamation.
- 10. Rehabilitate location according to BLM or State requirements.

Jicarilla Contract 148 18

F23, T25N-R5W, 1850' FNL, 1590' FEL API 3003922000 Federal Lease

Proposed PXA Wellbore Schematic



CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator Amoco Production Co. Well Name Jic 148 #18

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. For wells on Federal leases, Al Yepa with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Erwin Elote with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-3242.

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made:

A cement plug needs to be placed from 1480' to 1580' to cover the estimated top of the Nacimiento (1530').

BLM CONDITIONS OF APPROVAL

The following surface rehabilitation Conditions of Approval must be complied with as applicable, before this well can be approved for final abandonment (see 43 CFR 3162.3-4). Surface rehabilitation work shall be completed within one year of the actual plugging date. Notification for completion of this work can be submitted with a Sundry Notice. Questions? Call Pat Hester at (505) 761-8786.

- 1. All fences, production equipment, purchaser's equipment, concrete slabs, deadman (anchors), flowlines, risers, debris and trash must be removed from the location. Non-retrieved flowlines and pipelines will be abandoned in accordance with State Rule 714. Information supporting the non-retrieval will be included in the subsequent report or final abandonment Sundry Notice.
- 2. Production pits will be closed according to the Unlined Surface Impoundment Closure Guidelines, as approved in the Environmental Assessment of December 1993. Any oil stained soils can be remediated on-site according to these guidelines or disposed of in a an approved facility.
- 3. The well pad will be shaped to the natural terrain and left as rough as possible. All compacted areas and areas devoid of vegetation shall be ripped to a minimum of 12" in depth before reseeding.
- 4. Access roads will be shaped to conform to the natural terrain and left as rough as possible to deter vehicle travel. Access will be ripped to a minimum of 12" in depth, water barred and reseeded. All erosion problems created by the development must be corrected prior to acceptance of release. Water bars should be spaced as shown below along the fall line of the slope:

% Slope	Spacing Interval
Less than 20%	200'
2 to 5 %	150'
6 to 9 %	100'
10 to 15 %	50'
Greater than 15%	30'

- 5. All disturbed areas will be seeded with the prescribed certified seed mix (reseeding may be required). Seed mix must be certified weed free to avoid the introduction of noxious weeds. Refer to the original APD for seed mix.
- 6. Notify Surface Managing Agency seven (7) days prior to seeding so that they may be present to witness.
- 7. The period of liability under the bond of record will not be terminated until the well is inspected and the surface rehabilitation approved.

Other Surface Managing Agencies (SMA's) may vary slightly in their restoration requirements. It is your responsibility, as the operator, to obtain surface restoration requirements from other SMA's. We need to be provided with a copy of these requirements. Any problems concerning stipulations received from other SMA's should be brought to us.

On private land, a letter from the fee owner stating that the surface restoration is satisfactory will be provided to the office. Questions? Call Pat Hester at (505) 761-8786.