	UNITED STATES RTMENT OF THE INTERI REAU OF LID MANAGEMENT		5. LEASE DESIGNATION SF-080565		
SUNDRY N	NOTICES AND REPORTS ( proposals to drill or to deepen or plug b PLICATION FOR PERMIT—" for such pi	ON WELLS	6 IF INDIAN, ALLOTTER	ON TRIBE NAME	
OIL VV GAR			7. UNIT AGREEMENT NA	7. UNIT AGREEMENT NAME	
WELL WA WELL OTH	IER		8. PARM OR LEASE HAM	<b>B</b>	
Graham Royalty, Ltd.			Florance		
ADDRESS OF OPERATOR	, Lcu.		9. WBLL BO.		
1675 Larimer S	t Suite 400 Denve	r, Colorado 80202	9		
Location of WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			10. FIELD AND POOL, OR WILDCAT W.		
					1000' FSL & 10
1000 F2L & 10	OO. FEL		Sec. 5-25N-3W		
PERMIT NO. 15. BLEVATIONS (Show whether DF, RT, GR. etc.)		12. COUNTY OF PARISH	18. STATE		
30-039-22831	7216' GR	,	Rio Arriba	MM	
				1	
	k Appropriate Box To Indicate N		or Other Data		
NOTICE OF	INTENTION TO:	SUBI		<u> </u>	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	·;	
PRACTUBE TREAT	MILTIPLE COMPLETE	PRACTUBE TREATMENT	ALTERING CA		
SHOOT OR ACIDIZE	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMEN	T* -	
REPAIR WELL	CHANGE PLANE	(Other) Report res	rults of multiple completion of	m Well	
(Other) Squeeze Mesa	<u>verde &amp; Complete Dakota</u>	Completion or Reco	ompletion Report and Log for	m.)	
2. Squeeze l	ods, pump & tubing. Mesaverde perfs @ 5924-3			and somes perti-	
2. Squeeze   3. DO & pre 4. Retrieve	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'.	7' OA and 5415-28' (		**************************************	
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5	7' OA and 5415-28' ( 00#.	OA in 2 steps.	and goldes per li	
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'. t to PBTD @ <u>+</u> 8280'. Dakota perfs @ 3120-23',	7' OA and 5415-28' ( 00#.	OA in 2 steps.		
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'. t to PBTD @ <u>+</u> 8280'. Dakota perfs @ 3120-23',	7' OA and 5415-28' ( 00#.	OA in 2 steps.		
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'. t to PBTD @ <u>+</u> 8280'. Dakota perfs @ 3120-23',	7' OA and 5415-28' ( 00#.	OA in 2 steps.	IVED	
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing. Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'. t to PBTD @ <u>+</u> 8280'. Dakota perfs @ 3120-23',	7' OA and 5415-28' ( 00#.	OA in 2 steps.	1989 1. DIV	
2. Squeeze   3. DO & pre 4. Retrieve 5. Clean ou 6. Acidize	ods, pump & tubing.  Mesaverde perfs @ 5924-3 ssure test squeezes to 5 RBP @ 6114'. t to PBTD @ +8280'. Dakota perfs @ 3120-23', o production.	7' OA and 5415-28' ( 00#.	OA in 2 steps.  DECE SEP22 OIL CONDIST	1989 1989 1. DIV 3	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.