Form 3160-5

## UNITED STATES

FORM APPRO	CEDYED
Budget Bureau No.	1004-0135
Expires: March	31, 1993

3	udgal	DUN	ibi No	. lu	04-01	33
	Exp	ires:	March	: 31 <u>,</u>	1993	
			•	-		_

ne 1990) DEPARTMENT	r of the interior	Expires: March 31, 1993
	AND MANAGEMENT	5. Lease Designation and Serial No.
	- CORER TELL /	NM-40637
SUNDRY NOTICES A	AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to dril	Il or to deepen or reentry to a different reservoir	UEL N.M.
Use "APPLICATION FOR	R PERMIT—" for such proposals	
		7. If Unit or CA, Agreement Designation
SUBMIT	IN TRIPLICATE	
. Type of Well		8. Well Name and No.
		OSO CANYON FEDERAL "A" #1
Name of Operator	CAED BY ADACHE CODD)	9. API Well No.
MW PETROLEUM CORPORATION (MANA  Address and Telephone No.	GAED BY AFACHE CORY	30-039-23522
•	on, NM 87401 (505) 325-0318	10. Field and Pool, or Exploratory Area
304 N. BEHREND AVE., FARMINGTO  1. Location of Well (Footage, Soc., T., R., M., or Survey De		GAVILAN MAN/UND DAK
		11. County or Parish, State
1660' FNL 1790' FWL SEC 14, T	224N R2W	RIO ARRIBA, NM
2. CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	DN
X Notice of Intent	Abandonment	Change of Plans
(A) Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
C) Moscherg vehov	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
13. Describe Proceed or Completed Operations (Clearly state	all pertinent details, and give pertinent dates, including estimated thate of st	arting any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vert	ten ochan for mi tim ters mi cours bermen as an accus.	
MW PETROLEUM PROPOSES TO PL	UG AND ABANDON THE SUBJECT WELL. SI	EE ATTACHED PROCEDURE

FOR DETAILS.

OIL COM. DIV.

	Due -	සිං වි
170196	•	
4. I hereby verify that the foregoing is true and correct Signed	Tide PRODUCTION ENGINEER	Date 3/27/96
(This appear for Federal or State office use),  Approved by Robert Kert	Chief, Lands and Mineral Resources	- MAY 3 0 1996
Approved by	in attackal letter	

## Oso Canyon Federal A #1 Plugging Procedure

- 1. MIRU pulling unit. Install BOP. RIH with 2-3/8" workstring, retainer. Set retainer @ 7885' above Dakota perfs. Sting into retainer and squeeze 50 sx across perfs. Pull out of retainer and set 10 sx cement plug on top of retainer. POH.
- 2. RIH with 2-3/8" workstring, retainer. Set retainer @ 6685' above Gallup perfs. Sting into retainer and squeeze 50 sx across perfs. Pull ou of retainer and set 10 sx cement plug on top of retainer.
- 3. Spot 12 sx cement plug across the top of the Menefee formation (5180') from 5130' 5230'. Reverse out excess cement.
- 4. Spot 25 sx cement plug across the top of the Fruitland and PC formations (3250', 3348') from 3200' 3398'. Reverse out excess cement.
- 5. Spot 12 sx cement plug across the top of the Ojo Alamo formation (2990') from 2940' 3040'. Reverse out excess cement.
- 6. Spot 25 sx (150') cement plug across the base of the surface casing @309'. Reverse out excess cement.
- 7. Spot 15 sx surface plug.
- 8. Cut off wellhead, weld on plate, and set marker.

Well:

Oso Canyon Fed. A #1

Field:

Gavilan / Mancos

Location:

1660' FNL 1790' FWL Sec 14 - T24N - R2W Rio Arriba Co., New Mexico



KB - 7334'

Perforations:

Surface Csg: 8 5/8", 24# @ 309' Cement circ.

Gallup

6710' -6870' 6890' - 6982'

Dakota

7910'-7930'

Casing

5.5" 17# @ 8051' Cmnt circ.

Well:

Oso Canyon Fed. A #1

Field:


Gavilan / Mancos

Location:

1660' FNL 1790' FWL Sec 14 - T24N - R2W Rio Arriba Co., New Mexico







Cmnt circ.

Dakota 7910'-7930'

Gallup

Perforations:

6710' -6870'

6890' - 6982'

## CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

## Operator <u>MW PETROLEUM CORP</u> Well Name <u>OSO CANYON FED A #1</u>

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. For wells on Federal leases, Al Yepa with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Erwin Elote with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-3242.

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made:

18 sx of cement will be placed on top of the first retainer so that the top of the plug extends to 7727' which is 50' above the top of the Dakota formation.

A cement plug will be placed from 1400-1500'to cover the top of the Nacimiento formation.