Form 3160-5 (June 1990)

2. Name of Operator

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budger Bureau No. 1004-0135

	Expues:	March	1 71, 19	73
1 -250	Designan	on and	Serrai	No

NM 369513 17 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND	REPORTS ON WELLS
--------------------	------------------

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

N/A 7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Weil Oil Gas Weil Other

8. Weil Name and No. Ronald ACI Federal #1 9. API Well No.

YATES PETROLEUM CORPORATION 3. Address and Telephone No.

(505) 748-1471 10. Field and Pool, or Exploratory Area 105 South 4th St., Artesia, NM 88210

4. Location of Weil (Footage, Sec., T., R., M., or Survey Description) Unit P, 660' FSL & 660' FEL (SESE), Sec. 20-T24N-R11W

Wildcat Chaera 11. County or Parish, State

N/A

San Juan, NM

30-045-28282

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF ACTION TYPE OF SUBMISSION Change of Plans X Notice of Intent Abandonment New Construction Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing _ Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)

13. Describe Proposed or Completed Operations (Clearly state ail pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)4

Per telephone discussion with Steve Mason, BLM, Farmington, NM, propose to plug well as

Pull rods, pump and tubing. Pull RBP from 2000'.

GIH with tubing open ended and spot cement plugs (Class B $\rm w/2\%$ CaCl)

Plug #1 4416-4149' (25 sx). WOC and tag this plug.

Plug #2 1940-1747' (25 sx). WOC and tag this plug.

Plug #3 1145-215' (75 sx).

Plug #4 50' Surface plug

Install regulation abandonment marker.

Note: Will place heavy mud between plugs.

JUL 2 2 1991 OH CON. DIV.

SEE ATTACHED FOR

CONDITIONS () APPROVAL

		APPAOVED	
4. I hereofy certify that the foregoing is trule and correct Signed ()	Title Production Supervisor	Date 7-17-91	
(This space for Federal or State officie use) Approved by Conditions of approval, if any:	Tide	(bate)	
Title 18 U.S.C. Section 1001, makes it a crime for any person know	vingly and willfully to make to any department or agency of the	FARMANIA THE SOURCE APPLIED OF THE STATE OF	====

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: I Rungled ACI Feder

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Whik Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6#/gal slurry weight is to be used when using class B neat cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the tement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.
- All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.