

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SM 03733  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL.....		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

\_\_\_\_\_ 12-16 \_\_\_\_\_, 19 57

Well No. PC 312 is located 990 ft. from 10th [S] line and 1650 ft. from 10th [W] line of sec. 18

SE 1/4 34 18 26N 6W 107W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
South Blanco Hio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6668 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well spudded 12-9-57 at 9:00 AM.

Drilled 8 3/4" hole to 124'.

Reamed 15" hole to 118'.

Cemented 118' @ 5/8" 24# J-55 casing with 80 sacks. Cement circulated to surface. Plug down 7:00 PM 12-10-57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The G. Leary

Address Post Office Box 967

Farmington, New Mexico

By Frank Gray

Title Field Superintendent

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. This is essential for ensuring the integrity of the financial statements and for providing a clear audit trail. The records should be kept up-to-date and should be accessible to all relevant parties.

2. The second part of the document outlines the procedures for handling discrepancies. It is important to identify any errors as soon as possible and to investigate the cause of the discrepancy. Once the cause has been identified, the appropriate corrective action should be taken to prevent the error from recurring.

3. The third part of the document discusses the importance of regular communication between all parties involved in the financial process. This includes the management, the accounting department, and the external auditors. Regular communication helps to ensure that everyone is aware of the current status of the financial statements and any issues that may arise.

4. The fourth part of the document outlines the requirements for the external auditors. The auditors should be independent and should have the necessary qualifications and experience to perform the audit. The auditors should also be provided with all the necessary information and access to the records to enable them to perform their duties effectively.

5. The fifth part of the document discusses the importance of transparency and accountability in the financial process. This means that all transactions should be recorded accurately and should be available for review. It also means that the management should be held accountable for the accuracy of the financial statements and for any errors that may occur.