

F. Loc. 1190/N; 1850/W Elev. 6884 RDE 16 Spd. 3 11-70 Comp. 3-18-70 TD. 8037 PB. 7860
 Casing S. 10 3/4 @ 218 W 140 Sx. Int. 7 5/8 @ 3895 W 140 Sx. Pr. 4 1/2 @ 8037 W 500 Sx. T. _____ @ _____
 Csg. Perf. 7291-95, 7297-7301, Prod. Stim. SWF
598 ACF
 I.P. 595 MCF/D After 3 Hrs. SICP 1230 PSI After 7 Days GOR _____ Grav. _____ Ist Del. 12-16-70 ERNG

TOPS		NITD	Well Log	TEST DATA						
Kirtland		C-103	Plat	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104	Electric Log							
Pictured Cliffs	<u>3594</u>	<u>2-15-71</u>	C-122							
Cliff House	<u>4546</u>	Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout		PT	<u>Non-permeable</u> <u>R-4059</u> <u>(down hole commingling)</u> <u>1 Pan Am Pet Corp</u>							
Mancos	<u>5830</u>	<u>70</u>								
Gallup	<u>7291</u>	<u>NE 34-30</u>								
Sanostee										
Greenhorn	<u>7692</u>									
Dakota	<u>7914</u>									
Morrison										
Entrada										
			<u>160</u>							

P
 o
 ° BSMesa Gal. Co. RA S 10 T 26N R 4W UC Oper. AMOCO PROD. CO. Use Jic. Apache 102 No. 11