Packer cross f	low between		and Mesa Verde zones w	with reverse flo	w Check
comming	led product	ion and salvage san being used for Dako ressed then tubing	now being used for Ch ne. ota production will be will be rerun with eq	pulled out of	hole.
17. DERCRIBE PROPUSED of proposed work. I nent to this work.		ATIONS (Clearly state all pertine sally drilled, give subsurface loc	Completion or Recomp nt details, and give pertinent dates ations and measured and true vertic	<u> </u>	en.) e of starting any and zones perti-
TEST WATER SHOT- FRACTURE TREAT SHOOT OR ACIDIES REPAIR WELL	34	CLL OR ALTER CASING ULTIPLE COMPLETE BANDON* HANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING W ALTERING CA ABANDONMEN	AT°
16.	Check Approximation of intent	-	Nature of Notice, Report, or C	Other Data	
14. PERMIT NO.			6470 GR	Rio Arriba	New Mexico
	1980' F/S	and 660° F/W		Section 4, 26	
Caulkins Oil Company Bureau of LAND MANAGEMENT 3. ADDRESS OF OPERATOR P.O. Box 780 Farmington, New Mexico 87499 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface				Breech "E" 9. WBLL NO. 68-E 10. FIELD AND FOOL, OR WILDCAT Basin Dakota Otero Chacra - Blanco MV 11. SBC., T., R., M., OR BLK. AND	
		CES AND REPORTS		7. UNIT AGREEMENT HA	M E
	BUREAU	ENT OF THE INTER OF LAND MANAGEMEN	T	5. LEASE DECIGNATION NM 03551 G IF INDIAN, ALLOTTER	AND BERIAL NO.
Form 3160-5 November 1983) Formerly 9-331)		INITED STATES	SUBMIT IN TRIPLICATES (Other instructions on re-	Expires August	No. 1004-0135