Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE* (Other instructions on re-	Form approved. Budget Bureau No. 42-R1424.			
DEPAR	TMENT OF THE INTER	IOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.			
	GEOLOGICAL SURVEY		Contract 152 \			
CUNDDY NO	TICES AND DEDODES	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS						
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		Jicarilla Apache				
1.			7. UNIT AGREEMENT NAME			
WELL GAS WELL OTHER						
2. NAME OF OPERATOR			8 FARM OR LEASE NAME			
Occidental Petroleum Corporation			West			
3. ADDRESS OF OPERATOR			9. WELL NO.			
P. O. Box 234, Farmington, New Mexico 87401			3			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT			
At surface			South Blanco PC			
1750' FSL 1750' FWL			11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA			
			Car C TOCH DELL			
			Sec. 6, T26N, R5W			
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		F, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE			
	6671' GR		Rio Arriba N.M.			
16. Check A	Appropriate Box To Indicate N	Nature of Notice, Report, or C	Other Data			
			QUENT REPORT OF:			
	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL			
TEST WATER SHUT-OFF	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING			
FRACTURE TREAT	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT*			
SHOOT OR ACIDIZE	CHANGE PLANS	(Other)				
	CHANGE FLANS	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				
(Other)	DEFIATIONS (Clearly state all pertiner		including estimated date of starting any			
proposed work. If well is direct nent to this work.) *	ctionally drilled, give subsurface loca	tions and measured and true vertica	l depths for all markers and zones perti-			
nent to this work.)						
 Move in pulling 	unit					
1. Move in parting	unic		CCEII IN			
2 Swah wall to che	ack for hole in esa		/QII.FIV: N\			
Swab well to check for hole in csg			/ ULDELLED /			
3 If a hole in cso	is found cleanout we	11 to PBTD	111 1 2 1972			

- 4. Run 1 1/4" tbg with Baker packer
- Load 2 7/8" x 1 1/4" annulus with Baroid SF 100 csg pack materia
- Swab well in
- 7. Acidize well if necessary to restore production.





JUL 12 1972

U. S. GEOLOGICAL SURVEY DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct				
SIGNE Original signed by T. A. Dugan	TITLE	Engineer	DATE	7-11-72
Thomas A. Dugan				
(This space for Federal or State office use)				
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE	·